

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22004676/EPA3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MPC0009907
<b>Claimant Vehicle No :</b>	SKZ6339S	<b>Insured Vehicle No :</b>	SMW8236J
Date of Loss:	14/05/2022	Nature of Claim:	TP
		Claim No:	MPC2022D0002551

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKZ6339S</b>	Engine No:	27682430462089
Make & Model:	MERCEDES-BENZ S320L, 3.0 (A)	Chassis No:	WDD2221622A291776
Reg. Date:	10/11/2016 (Man. Year: 2016)	Odometer:	108682 km
Colour:	Black		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,929.99	6,148.78	2,781.21	31.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	3,160.00	880.00	21.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,969.99</b>	<b>9,308.78</b>	<b>3,661.21</b>	<b>28.23</b>
<b>+ GST 7.00/7.00% (S\$)</b>	907.90	651.61	256.29	28.23
<b>Nett Amount (S\$)</b>	<b>13,877.89</b>	<b>9,960.39</b>	<b>3,917.50</b>	<b>28.23</b>
<b>+ Car Rental (6.0 x S\$170.00/day + 7.00% GST) (S\$)</b>		1,091.40		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>11,053.79</b>		

INSPECTION

Date of Assignment:	18/05/2022	
Date Inspected:	19/05/2022 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2022)
Parts:	143	MERCEDES-BENZ S320L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ6339S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH/F HEADLAMP	Cut	6,141.81 FS	*6,141.81 FS
2	1		*FRT BUMPER	Repair	1,987.00 FS	*- FS
3	1		*RH/F BOTTOM GRILLE	Not Necessary	145.48 FS	*- FS
4	1		*RH/F BOTTOM GRILLE GARNISH	Not Necessary	120.79 FS	*- FS
5	1		*RH/F PARKING SENSOR	Not Necessary	191.59 FS	*- FS
6	1		*RH/F PARKING SENSOR SEAL	Necessary	6.97 FS	*6.97 FS
7	1		*RH/F BASIC MOUNTING FOR BUMPER	Not Necessary	321.37 FS	*- FS
8	1		*RH/F BUMPER BRACKET	Not Necessary	14.98 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					8,929.99	6,148.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	480.00	480.00
2	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
3	REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
4	RESPRAY FRONT BUMPER & FRONT RIGHT FENDER	New	2,000.00	1,600.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,040.00</b>	<b>3,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >