

Vehicle Damage Assessment Report for [SKZ6339S]

Estimate Created: 18/05/2022 10:11 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 23/12/2022 00:22 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	S-Class
Engine Type			
License Plate Number	SKZ6339S	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$9308.78 with 5 days for repair

Insurlogic 1 (23/12/2022 00:21)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
HEADLAMP RH		1	6141.81	0.00 %	6,141.81
PARKING SENSOR SEAL		1	6.97	0.00 %	6.97

Parts Subtotal 6,148.78

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
DIAGNOSTIC	RnR	480.00	0.00 %	480.00
CHECK HEADLAMP FOCUS AND ADJUSTMENT	RnR	120.00	0.00 %	120.00
REPLCAE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	960.00	0.00 %	960.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	1600.00	0.00 %	1,600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,560.00

Paint Labor Subtotal 1,600.00

Labor Subtotal 3,160.00

Summary

Repair Cost 9,308.78

Discount(0 %) (0.00)

9,308.78

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 9,308.78