



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SKZ6339S

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information
WIP No 56836
Reg No/Reg Date SKZ6339S / 10/11/2016
Date In/Mileage / 0
Chassis No WDD2221622A291776
Engine No 27682430462089
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 021 183 Magnetite B/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	17/05/2022/ 10:15		305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M BPNSUN POLICY NO/ACC DATE : DMPCSNW00201692102 / 14-05-2022 DRIVE IN: 17-05-2022 / TP CAR NO: SMN8236J (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				480.00 ✓
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00 ✓
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				960 1440.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER			0.02 1600	2000.00
M RH/F HEADLAMP	1.00	6141.81	00.00	6141.81 ✓
M FRT BUMPER	1.00	1987.00	00.00	1987.00
M RH/F BOTTOM GRILLE	1.00	145.48	00.00	145.48
M RH/F BOTTOM GRILLE GARNISH	1.00	120.79	00.00	120.79
M RH/F PARKING SENSOR	1.00	191.59	00.00	191.59
M RH/F PARKING SENSOR SEAL	1.00	6.97	00.00	6.97 ✓
M RH/F BASIC MOUNTING FOR BUMPER	1.00	321.37	00.00	321.37
M RH/F BUMPER BRACKET	1.00	14.98	00.00	14.98

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Stew (CLKK)

19/5/22 2.17pm

WRL PL

5 days

PIP

Mj Bl Sy

Confirmed & accepted by

Nett 12,969.99
7% GST on 12969.99 907.90
Total Payable 13,877.89

LKK Auto Consultants hence notify
the Repairer of the following:

To resurvey before repair spray painting
To display damaged part(s) during resurvey

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer
Signature:
Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 1 of 1