



Mercedes-Benz

## Finalization

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKZ6339S

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711  
63476100

Steve

## Vehicle &amp; Document Information

WIP No 56836  
Reg No/Reg Date SKZ6339S / 10/11/2016  
Date In/Mileage 19/05/2022 / 108682  
Chassis No WDD2221622A291776  
Engine No 27682430462089  
Make/Model MB/MB S 320 L SEDAN (V222)  
Colour/Trim 021 183 Magnetite B/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	27/07/2022/ 19:13		305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : DMPCSNW00201692102 // 14-05-2022 DRIVE IN: 17-05-2022 // TP CAR NO: SMW8236J (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: 19-05-2022 // LKK STEVE BY/AUTHORIZED ON : GABRIEL WEE // 19-05-2022				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				480.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				960.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER			0.05	1600.00
X RH/F HEADLAMP	1.00	6141.81	00.00	6141.81
X RH/F PARKING SENSOR SEAL	1.00	6.97	00.00	6.97

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed &amp; accepted by

Nett 9,308.78  
7% GST on 9308.78 651.61  
Total Payable 9,960.39

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg