

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

YIANXIN

Lentor Plain
ore 786548

Not Notified

11/10/2021

Resurvey After Painting

3 days

Date : 15/10/2021

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : HONDA VEZEL / SLA 5860 D	
	rear boot lid	12 1,264.90 X
	rear boot emblem "LOGO"	1 62.80
	rear bumper	1 895.70
	rear bumper side pad	1 456.20
	rear bumper side retainer	1 65.40
	rear bumper dust cover	1 130.10 X
	rear bumper lower dust cover	1 315.60 X
	rear bumper reflector	1 316.50
	rear end panel	1 577.60 X
	rear wheel arch protector	1 419.40
	rear end panel garnish	1 473.20 X
	sub-total	4,977.40
	less 20%	995.48
	sub-total	3,981.92
	windscreen glass sealant	1 60.00 X
	reverse sensor	1 400.00 X
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	4000 800.00
	To check wiring system.	15/ 50.00
	To apply putty & spray painting on affected areas.	320/ 650.00
	To apply rust proofing on affected areas.	100.00 X
	To apply water proof sealant on affected areas.	100.00 X
	To replace rear windscreen glass.	140.00 X
	total	1,840.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer s.nett
Signature: s.nett
Date: