



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22004681/Uty3n2	
			Date: 30/05/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6274X	Veh. Inspected	FBS 5972M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/22/2047	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	18/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX 155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3SG6420MJ006788	Colour	GREY
	Odometer	13317 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120-70-14	MICHELIN	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140-60-14	MICHELIN	7 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/05/2022	Inspection Date	19/05/2022
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	