

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2022)
Parts:	M1-SUV	BMW X3 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW2703S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER (NPA)	Scratched	0.00 FL	*- FL
2	1		*FRONT BUMPER	Cut	1,627.70 FL	*1,627.70 FL
3	10		*FRONT BUMPER CLIP	Necessary	76.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					1,703.70	1,667.70
- List Item Discount on L Items 5.00/5.00% (S\$)					81.39	81.39
Total Parts (S\$)					1,622.31	1,586.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FRONT AFFECTED PORTION	New	400.00	400.00
2	PAINTING FRONT AFFECTED PORTION	New	500.00	400.00
Gross Labour Cost (S\$)			900.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >