

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Loke Wei Yiang

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/05/2022
Vehicle Reg. No.:	SHC2142A	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Vehicle Reg. Date:	06/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2B82915	Chassis No:	JTDKB3FU403077645
Odometer:	465673 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,558.62
Miscellaneous Items	11.00
Labour	1,120.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,689.62
+ GST 7.00% (\$\$)	188.27
Nett Amount (\$\$)	2,877.89

This claim is handled by: LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 May 2022)

Parts: 144 **TOYOTA PRIUS 1.5 HYBRID (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **ComfortDelGro Engineering Pte Ltd/SHC2142A/17/05/2022 13:24**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER X <i>repair</i>	25.00	0.00	*503.04 FL
2	1		*REAR BUMPER CLIPS X	25.00	0.00	*22.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH X	25.00	0.00	*94.80 FL
4	1		*REAR BUMPER SIDE RETAINER RH X	25.00	0.00	*94.80 FL
5	1		*REAR BUMPER TOWING COVER X	25.00	0.00	*82.70 FL
6	1		*REAR BUMPER REINFORCEMENT X	25.00	0.00	*378.32 FL
7	1		*REAR BUMPER LOWER COVER / <i>be</i>	491.18 25.00	0.00	*654.90 FL ✓
8	1		*REAR BUMPER ADVERTISEMENT STICKER / <i>ml</i>	0.00	0.00	*50.00 F ✓
9	1		*REAR BUMPER REVERSE SENSOR X <i>nm</i>	0.00	0.00	*135.70 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,016.26
- List Item Discount on L Items (S\$)	457.64
Total Parts (S\$)	1,558.62

ComfortDelGro Engineering Pte Ltd/SHC2142A/17/05/2022 13:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			11.00
1	1	OD/TP Case (Insurer) ✓	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 700.00
2	SPRAY PAINTING CHARGE	New	250 300.00
3	REMOVE/ REFIX REVERSE SENSOR	New	40 60.00
4	TUFF KOTE	New	MX 60.00
Gross Labour Cost (S\$)			1,120.00

ComfortDelGro Engineering Pte Ltd/SHC2142A/17/05/2022 13:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

950

4/5
20 days.

After repair photos.

Gene Ong

19/15/22

1:30 pm.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: