



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC22002583/Rvy3-1

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22002583/Rvy3~~

Date: ~~21/03/2022~~ 18/05/2022

Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GW 1883H	Veh. Inspected	SLZ 4929R
Policy No.		Coverage (\$)	0.00
Claim No.	21/22/22/VC05/025567	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	21/03/2022 18/05/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/03/2022	Inspection Date	22/03/2022
Survey held at	60 JALAN LAM HUAT #02-28 CARROS CENTRE		
Repairer	LONG VIEW MOTOR WORKS		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.