

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB22004690/RPA3Q2**Date:** 18/01/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0000974
<b>Claimant Vehicle No :</b>	SND3536P	<b>Insured Vehicle No :</b>	SLM7197J
Date of Loss:	04/05/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0002261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SND3536P</b>		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR2N24151
Reg. Date:	23/12/2021 (Man. Year: 2021)	Chassis No:	ZWR800512064
Colour:	Black	Odometer:	30764 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,535.67	2,609.60	1,926.07	42.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,170.00	470.00	28.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,175.67</b>	<b>3,779.60</b>	<b>2,396.07</b>	<b>38.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	432.30	264.57	167.73	38.80
<b>Nett Amount (S\$)</b>	<b>6,607.97</b>	<b>4,044.17</b>	<b>2,563.80</b>	<b>38.80</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,451.62</b>		

INSPECTION

Date of Assignment:	17/05/2022	
Date Inspected:	17/05/2022	Inspected At: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND3536P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	2,337.80 FL	*2,337.80 FL
2	1		*REAR TAILGATE GLASS RH MOULDING	Necessary	52.80 FL	*52.80 FL
3	1		*REAR TAILGATE GLASS LH MOULDING	Necessary	52.80 FL	*52.80 FL
4	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	60.80 FL	*60.80 FL
5	1		*REAR TAILGATE INNER TRIMBOARD	Not Necessary	605.10 FL	*- FL
6	1		*REAR TAILGATE LOCK	Not Necessary	846.50 FL	*- FL
7	1		*REAR BUMPER	Deformed	573.60 FL	*573.60 FL
8	1		*REAR BUMPER PARKING SENSOR	Cut	368.10 FS	*200.00 FS
9	1		*REAR BUMPER RETAINER SENSOR	Not Necessary	86.30 FL	*- FL
10	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
11	1		*REAR END PANEL	Repair	779.40 FL	*- FL
12	1		*REAR WINDSCREEN GUM	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,898.20	3,392.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,362.53	783.20
Total Parts (\$\$)	4,535.67	2,609.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO REPAIR DAMAGES	New	680.00	400.00
3	TO SPRAY PAINTING	New	780.00	650.00
<b>Gross Labour Cost (S\$)</b>			<b>1,640.00</b>	<b>1,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >