

Vin's

Estimated Cost of Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Attention To : India International Insurance
Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Claim Details

Case Ref. No. : TP/052022/5405
Date : 17-05-2022
Accident Date : 04-05-2022

Vehicle Details

Make & Model : Toyota NOAH HYBRID 1.8X CVT
7 SEATER
Chassis No : ZWR800512064
Registration No : SND3536P

Third Party Vehicle Details

Registration No : SLM7197J

S/N	Description	Qty	Amount (\$S)
1	REAR TAILGATE <i>bt</i>	1.00	\$2,337.80
2	REAR TAILGATE GLASS RH MOULDING <i>re</i>	1.00	\$52.80
3	REAR TAILGATE GLASS LH MOULDING <i>re</i>	1.00	\$52.80
4	REAR TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM <i>re</i>	1.00	\$60.80
5	REAR TAILGATE INNER TRIMBOARD <i>X nn</i>	1.00	\$605.10
6	REAR TAILGATE LOCK <i>X nn</i>	1.00	\$846.50
7	REAR BUMPER <i>de</i>	1.00	\$573.60
8	REAR BUMPER PARKING SENSOR <i>? cut</i>	1.00	\$490.80
9	REAR BUMPER ANTENNA SENSOR <i>X nn</i>	1.00	\$86.30
10	REAR BUMPER CLIPS @ \$5.50 <i>re</i>	10.00	\$55.00
11	REAR END PANEL <i>? repair</i>	1.00	\$779.40

Discount: -25%

- 12 REAR WINDSCREEN GUM *re*
- 13 TO REMOVE AND REFIX REAR WINDSCREEN *re*
- 14 TO REPAIR DAMAGES
- 15 TO SPRAY PAINTING

Subtotal w/o GST:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

2349.60
200.00
1230.00
3779.60

S/N-200

3132180

259
2349.60

\$5,940.90
(\$1,485.23)

\$4,455.67

~~\$80.00~~ 60

~~\$180.00~~ 120

~~\$680.00~~ 400

~~\$780.00~~ 400

\$6,175.67

850

+ 200 = 650

Rasm
Hp 90010068

4 days

P/P

17/05/22 P1625

Reas before paint