

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8799 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	? 350 250.
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	? 480 880. <i>h/s.</i>
4	TO DISMANTLE AND RENEW FRONT BUMPER. BONNET, AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 1350
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 2,500.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,472.00	

2.
 + ~~1~~ days

Car in

15/6/22

wip: 23911

PREMIUM AUTOMOBILES

Beroi: 

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIR - Admin
 - 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd.</i>	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 612.00	x
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 79.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>M</i>	1	\$ 254.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 144.00	+
7	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,478.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 302.00	+
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 139.00	?
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 899.00	?
11	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 508.00	?
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 82.00	x
13	FRONT BUMPER TOP COVER <i>crushed</i>	1	\$ 143.00	2
14	CAUTION STICKER <i>3 new</i>	1	\$ 16.00	2
15	AIR COND STICKER <i>3 new</i>	1	\$ 9.00	2
16	FRONT BUMPER LOCK CARRIER BRACKET <i>crushed</i>	1	\$ 154.00	2
17	FRONT BUMPER SUPPORT (LH / RH) <i>Del'd.</i>	2	\$ 64.00	2
18	FRONT BUMPER POP RIVET <i>new</i>	4	\$ 4.00	✓
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 530.00	+
20	FRONT BUMPER SEAL RING <i>new</i>	4	\$ 10.00	+
SUB TOTAL SPARE PARTS		:	\$ 8,023.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN - LH / RH <i>new</i>	2	\$ 273.00	x
22	HORN BRACKET - LH / RH	2	\$ 66.00	x
23	BONNET <i>Painted</i>	1	\$ 3,425.00	✓
24	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 431.00	x
25	BONNET HINGE - LH / RH ?	2	\$ 680.00	?
26	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$ 93.00	✓
27	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 112.00	x
28	BONNET LOCK ?	2	\$ 455.00	?
29	BONNET BOWDEN CABLE - UPPER <i>new</i>	1	\$ 64.00	2 ✓ <i>sls</i>
30	BONNET RELEASE CABLE COVER ?	1	\$ 11.00	?
31	BONNET BOWDEN CABLE - LOWER ?	1	\$ 64.00	?
32	BONNET RELEASE LEVER ?	1	\$ 15.00	?
33	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 522.00	x
34	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 164.00	x
35	HEADLIGHT LH / RH <i>2H cracked</i>	2	\$ 16,588.00	8294. <i>sls</i>
36	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 462.00	x
37	LIFT CYLINDER BRACKET - LH / RH <i>new</i>	2	\$ 14.00	x
38	LIFT CYLINDER CORRUGATED PIPE <i>new</i>	1	\$ 107.00	x
39	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 21.00	?
40	LOCK CARRIER ?	1	\$ 1,127.00	x
SUB TOTAL SPARE PARTS		:	\$ 24,694.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	A/C CONDENSER <i>Dented</i>	1	\$ 683.00	<i>✓</i>	<i>h/s</i>
42	RADIATOR COOLANT <i>Not mtr</i>	6	\$ 282.00	<i>?</i>	
43	RADIATOR AIR GUIDE OUTER - LH / RH <i>?</i>	2	\$ 54.00	<i>?</i>	
44	RADIATOR AIR GUIDE INNER <i>LH / RH</i> <i>Dented</i>	2	\$ 28.00	<i>✓</i>	<i>h/s</i>
45	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	<i>?</i>	
46	RADIATOR AIR GUIDE - LOWER <i>?</i>	1	\$ 25.00	<i>?</i>	
47	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i>	
48	SUNDRIES <i>?</i>		\$ 350.00	<i>?</i>	
TOTAL SPARE PARTS		:	\$ 34,228.00		
TOTAL LABOUR CHARGES		:	\$ 9,472.00		
GRAND TOTAL		:	\$ 43,700.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.