


PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Vera.

\$20520.48.

8 Days. M/S.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8799 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	? 350 250.350
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	? 1400 780. M/S.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 ✓ 13500
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 2,500.00	1100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 9,472.00	


2.
+ ~~1~~ days

Car in

15/6/02

wip: 23911

PREMIUM AUTOMOBILES

Beroi: 

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

AZG - Admin
- 6 days

DAMAGED PARTS & PRICES					REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
1	FRONT BUMPER <i>Del'd.</i>	1	S	2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS <i>ren</i>	1	S	612.00	X
3	FRONT BUMPER SECURING STRIP <i>the ren</i>	2	S	79.00	? X
4	FRONT BUMPER GRILLE - CENTER <i>ren</i>	1	S	219.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>ren</i>	1	S	254.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>ren</i>	2	S	144.00	+
7	RADIATOR GRILLE <i>crushed</i>	1	S	1,478.00	✓ 1182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>ren</i>	2	S	302.00	+
9	FRONT BUMPER FOAM FILLER PIECE <i>the ren</i>	1	S	139.00	? X
10	FRONT BUMPER REINFORCEMENT BEAM <i>the ren</i>	1	S	899.00	? X
11	FRONT BUMPER BRACKET - LH / RH <i>the ren</i>	2	S	508.00	? X
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>ren</i>	2	S	82.00	+
13	FRONT BUMPER TOP COVER <i>crushed</i>	1	S	114 143.00	✓ } R.S.
14	CAUTION STICKER <i>3 over</i>	1	S	12.40 16.00	✓
15	AIR COND STICKER	1	S	6.64 9.00	✓
16	FRONT BUMPER LOCK CARRIER BRACKET <i>crushed</i>	1	S	122.80 154.00	✓
17	FRONT BUMPER SUPPORT (LH / RH) <i>Del'd.</i>	2	S	51.04 64.00	✓
18	FRONT BUMPER POP RIVET <i>ren</i>	4	S	4.00	✓ 2.88
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>ren</i>	2	S	530.00	+
20	FRONT BUMPER SEAL RING <i>ren</i>	4	S	10.00	+
SUB TOTAL SPARE PARTS			:	\$ 8,023.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN - LH / RH <i>Ren</i>	2 S	273.00	X
22	HORN BRACKET - LH / RH	2 S	66.00	X
23	BONNET <i>Scuffed</i>	1 S	3,425.00	✓ 2740
24	BONNET ATTACHMENT PARTS <i>Ren</i>	1 S	431.00	+
25	BONNET HINGE - LH / RH <i>Not Rec</i>	2 S	680.00	? X
26	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Ren</i>	3 S	93.00	✓ 73.20
27	BONNET STRIKER - LH / RH <i>Ren</i>	2 S	112.00	+
28	BONNET LOCK <i>Not Rec</i>	2 S	455.00	? X
29	BONNET BOWDEN CABLE - UPPER <i>Damage</i>	1 S	64.00	✓ <i>88.5</i> 50.56
30	BONNET RELEASE CABLE COVER <i>Not Rec</i>	1 S	11.00	? X
31	BONNET BOWDEN CABLE - LOWER <i>Not Rec</i>	1 S	64.00	? X
32	BONNET RELEASE LEVER <i>Not Rec</i>	1 S	15.00	? X
33	FRONT WHEEL HOUSING LINER - LH / RH <i>Ren</i>	2 S	522.00	X
34	FRONT WHEEL SPOILER - LH / RH <i>Ren</i>	2 S	154.00	+
35	HEADLIGHT (LH / RH) <i>2H cracked</i>	2 S	16,588.00	? <i>8294. 88.5</i> 6635.20
36	LIFT CYLINDER - LH / RH <i>Ren</i>	2 S	462.00	+
37	LIFT CYLINDER BRACKET - LH / RH <i>Ren</i>	2 S	14.00	X
38	LIFT CYLINDER CORRUGATED PIPE <i>Ren</i>	1 S	107.00	✓
39	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Not Rec</i>	1 S	21.00	? X
40	LOCK CARRIER <i>Not Rec</i>	1 S	1,127.00	+
SUB TOTAL SPARE PARTS		:	\$ 24,694.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	A/C CONDENSER <i>Dented</i>	1 S	683.00	<i>✓</i>	<i>sls</i> 546
42	RADIATOR COOLANT <i>Not new</i>	6 S	282.00	? X	
43	RADIATOR AIR GUIDE OUTER - LH / RH <i>Not new</i>	2 S	54.00	? X	
44	RADIATOR AIR GUIDE INNER <i>LH / RH Behind</i>	2 S	28.00	<i>✓</i>	<i>sls</i> 21.76
45	RADIATOR AIR GUIDE - UPPER <i>Not new</i>	1 S	19.00	? X	
46	RADIATOR AIR GUIDE - LOWER <i>Not new</i>	1 S	25.00	? X	
47	FRONT NO PLATE <i>Dented</i>	S/N S	60.00	<i>✓</i> 60	
48	SUNDRIES <i>New</i>	S	350.00	? 18	
TOTAL SPARE PARTS		:	\$ 34,228.00		
TOTAL LABOUR CHARGES		:	\$ 9,472.00		
GRAND TOTAL		:	\$ 43,700.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.