

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0389/2022/JT
DATE : 13-May-22
WIP : 23911

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

8 days exclude 1 Sunday

Johnny Boo 19 Sep 22

OWNER'S NAME : MR CHAN ZHICONG DAMIEN (ZENG ZHICONG DAMIEN)
ADDRESS : 93 MEYER ROAD
#22-03
SINGAPORE 437986
TELEPHONE : HP +65 96617895
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070051983-01
VEHICLE NO : **SMS 8799 Y**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 19/3/2020
ENGINE NO : CVK 087542
CHASSIS NO : WAUZZZF48KA114978
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-May-22
PLACE OF ACCIDENT : SLIP ROAD AT CTE TOWARDS MOULMEIN ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8799 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$ 250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,400.00	\$ 780.00
4	TO DISMANTLE AND RENEW FRONT BUMPER. BONNET, AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$	2,500.00	\$ 1,100.00
6	ADDED LABOUR -	\$	1,660.00	\$ 1,660.00
7	ADDED LABOUR - SEE ATTACHED	\$	1,750.00	\$ 800.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 12,882.00	\$ 6,262.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00		
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 144.00		
7	RADIATOR GRILLE	1	\$ 1,478.00	\$	1,182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 302.00		
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00		
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
11	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00		
12	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00		
13	FRONT BUMPER TOP COVER	1	\$ 143.00	\$	114.00
14	CAUTION STICKER	1	\$ 16.00	\$	12.40
15	AIR COND STICKER	1	\$ 9.00	\$	6.64
16	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$	122.80
17	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	\$	51.04
18	FRONT BUMPER POP RIVET	4	\$ 4.00	\$	2.88
19	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 530.00		
20	FRONT BUMPER SEAL RING	4	\$ 10.00		
SUB TOTAL SPARE PARTS		:	\$ 8,023.00	\$	3,393.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	3,393.76
21	HORN - LH / RH	2	\$ 273.00		
22	HORN BRACKET - LH / RH	2	\$ 66.00		
23	BONNET	1	\$ 3,425.00	\$	2,740.00
24	BONNET ATTACHMENT PARTS	1	\$ 431.00		
25	BONNET HINGE - LH / RH	2	\$ 680.00		
26	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	\$	73.20
27	BONNET STRIKER - LH / RH	2	\$ 112.00		
28	BONNET LOCK	2	\$ 455.00		
29	BONNET BOWDEN CABLE - UPPER	1	\$ 64.00		
30	BONNET RELEASE CABLE COVER	1	\$ 11.00		
31	BONNET BOWDEN CABLE - LOWER	1	\$ 64.00	\$	50.56
32	BONNET RELEASE LEVER	1	\$ 15.00		
33	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 522.00		
34	FRONT WHEEL SPOILER - LH / RH	2	\$ 164.00		
35	HEADLIGHT - LH / RH	2	\$ 16,588.00	\$	6,635.20
36	LIFT CYLINDER - LH / RH	2	\$ 462.00		
37	LIFT CYLINDER BRACKET - LH / RH	2	\$ 14.00		
38	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
39	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
40	LOCK CARRIER	1	\$ 1,127.00		
SUB TOTAL SPARE PARTS		:	\$ 24,694.00	\$	12,892.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8799 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	12,892.72
41	A/C CONDENSER	1	\$ 683.00	\$	546.00
42	RADIATOR COOLANT	6	\$ 282.00		
43	RADIATOR AIR GUIDE OUTER - LH / RH	2	\$ 64.00		
44	RADIATOR AIR GUIDE INNER - LH / RH	2	\$ 28.00	\$	21.76
45	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00		
46	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00		
47	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
48	SUNDRIES		\$ 350.00	\$	18.00
TOTAL SPARE PARTS		:	\$ 34,228.00	\$	13,538.48
TOTAL LABOUR CHARGES		:	\$ 12,882.00	\$	6,262.00
GRAND TOTAL		:	\$ 47,110.00	\$	19,800.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-19/08/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0389/2022/JT 21-Jun-22 CHANG 1 of 1 SMS 8799 Y AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO REPAIR LHS FRONT FENDER.		\$ 700.00	\$ 250.00
2	TO RESPRAY LHS FRONT FENDER.		\$ 1,050.00	\$ 550.00
	GRAND TOTAL		\$ 1,750.00	\$ 800.00

For Premium Automobiles Pte Ltd

Authorized Signature



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0389/2022/JT 21-Jun-22 GLORY 1 of 1 SMS 8799 Y AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.		S/N \$ 560.00	\$ 560.00
2	TO RESPRAY BOTH FRONT DOORS.		\$ 1,100.00	\$ 1,100.00
GRAND TOTAL			\$ 1,660.00	\$ 1,660.00

For Premium Automobiles Pte Ltd

Authorized Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT