



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 18.05.2022

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SME8909X HONDA VEZEL (HYBRID)
(Registration date: 22.10.2018)

To Supply

1) 1pc	Rear bumper lower garnish / <i>DD</i>	\$	985.00	762 ✓
2) 1pc	Left rear bumper / <i>CR</i>	\$	245.00	180 ✓
3) 1pc	Rear bumper left reflector / <i>BR</i>	\$	189.00	141 ✓
4) 1pc	Tailgate / <i>DD</i>	\$	1,100.90	953 ✓
5) 1pc	Tailgate "H" emblem / <i>NN</i>	\$	38.00	
6) 1pc	Tailgate "Vezel" emblem / <i>MC</i>	\$	60.00	✓
7) 1pc	Tailgate "Hybrid" emblem / <i>MC</i>	\$	60.00	✓
8) 1pc	Rear end panel ? X Repair	\$	520.00	
2156		Sub total Parts	\$	3,197.90
-20%		Less: 20% discount	\$	(639.58)
1724.80			\$	2,255.12

To supply S.Nett Parts

1) 1 set	Rear bumper clips / <i>MC</i>	\$	30.00	✓
2) 1 set	Reverse sensors / <i>SL</i>	\$	200.00	✓
3) 1 tube	Rear glass sealant / <i>MC</i>	\$	45.00	
4) 1set	Rear glass moulding (4pcs) / <i>MC</i>	\$	200.00	
390				
Sub total S.Nett Parts		\$	475.00	

L/charges

- 1) To tuff kote affected portion. \$ 30 50.00
- 2) To transfer tailgate trim board, handle, mechanism parts & etc. \$ 30 60.00
- 3) To remove & refit rear glass. \$ 120.00 ✓
- 4) To remove & replace reverse sensors & refit rear camera, check wiring. \$ 30 80.00
- 5) To knock & repair rear end panel. Remove rear bumper lower garnish, left rear bumper, tailgate & etc. Replace the above parts, adjust & align rear bumper & tailgate \$ 420 700.00 600 ✓
- 6) To putty respray painting tailgate's inlet & oute, rear end panel & left rear bumper. To polish. \$ 400 600.00 ✓

1410

P/P - 3524.80

Sub total L/charges	\$ 1,610.00
Estimated Grand Total	\$ 4,340.12

Steve (LKK)

19/5/22, 1.19pm

m R

4/5 P/P

by M y

5 # 4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: