



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI22004700/Kny3q2 Date: 16/08/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 8876C	Veh. Inspected	SFC 9383Z
Policy No.	D-21098839MFCV/19	Coverage (\$)	0.00
Claim No.	D22001457MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	19/05/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 6 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6GL1071H0126880	Colour	METALLIC DARK BLUE
Odometer	97069 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	GOODYEAR	8 mm
L/H Front Tyre	225/55 R17	GOODYEAR	8 mm
R/H Rear Tyre	225/55 R17	GOODYEAR	8 mm
L/H Rear Tyre	225/55 R17	GOODYEAR	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/05/2022	Inspection Date	19/05/2022
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	