

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Notified
 11pm @ 3750hr
 Presurvey After Rain
 4 days*

To: First Capital Insurance Limited

Policy No: _____ Third Party

Accident Date : 11.05.2022

Date: 18.05.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Mazda 6" Reg. No. SFC9383Z Claiming Against Your Insured Veh. No. GBB8876C			
1pc	Front Bumper <i>1026.50</i>		<i>CM</i> 1,396.00 ✓
14pcs	Front Bumper Clips	4.50	<i>nn</i> 63.00 ✓
1pc	Front Bumper Bracket RH		<i>sn</i> 145.00 X
1pc	Front Bumper Corner Retainer RH		<i>CM</i> 95.00 ✓
6pcs	Front Bumper Top Rivets	6.00	<i>nn</i> 36.00 X
1pc	Headlamp RH (HID) <i>2970</i>		<i>My CM</i> 2,970.00 ✓
1pc	Wiper Tank		<i>sn</i> 185.00 X
1pc	Wiper Tank Motor		<i>sn</i> 146.00 X
1pc	Front Fender RH <i>462</i>		<i>sn</i> 462.00 ✓
1pc	Front Fender Shield RH <i>148.10</i>		<i>CM</i> 250.00 ✓
8pcs	Front Fender Shield Clips	4.80	<i>nn</i> 38.40 ✓
	Less 20%		5,786.40
			1,157.28
			4,629.12
	To Conduct Electrical Check, Focus Headlamp		30.00 <i>200</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		50.00 <i>300</i>
	Labour Charge - Panel Beating, Repairing of Front Fender Inner Panel & Part Replacement		600.00 <i>4000</i>
	To Respray Affected Areas		580.00 <i>4000</i>
	Total :		5,889.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company