## Yan (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>

**Sent:** Wednesday, 18 May 2022 5:55 PM assignments@lkkauto.com; 'SUR'

**Cc:** Summer (LKK Auto)

Subject: FW: SOMPO REF:CMTD2201679/SYH/RE: URGENT ACCIDENT INVOLVING SKD9900S &

SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022

AT ABOUT 1606 HOURS || PD.192604

**Attachments:** WinZip Compressed Attachments.zip

Dear LKK AUTO,

Kindly assist to arrange to conduct the mentioned motor survey.

Both SAS reports as attached.

Password: SOMPO1679

Note: \* Currently working from home.

Best Regards Irene Henry Claims Division

D: 6322 4618 | T: 6461 6555



## Innovation for Wellbeing

#### Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623 **Website:** www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Henry, Irene James

**Sent:** Wednesday, May 18, 2022 5:51 PM

Cc: aaron tan <aarontkj.sk@gmail.com>; Eldredgoh@gmail.com

**Subject:** RE: SOMPO REF:CMTD2201679/SYH/RE: URGENT ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS || PD.192604

Without Prejudice

Our Reference: CMTD2201679/SYH

Your Reference: PD.192604

Dear Sirs.

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO CONSULTANTS PTE LTD** to conduct the prerepair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

#### Note: \* Currently working from home.

Best Regards Irene Henry Claims Division

**D**: 6322 4618 | **T**: 6461 6555



# Innovation for Wellbeing

#### Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <u>here</u> for our Privacy Policy.

From: SL LAW PRS prs@sllaw.com.sg>
Sent: Wednesday, May 18, 2022 10:28 AM

To: Henry, Irene James <irene.henry@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: aaron tan <aarontki.sk@gmail.com>; Eldredgoh@gmail.com

Subject: RE: SOMPO REF:CMTD2201679/SYH/RE: URGENT ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS || PD.192604

Importance: High

**CAUTION**: This Email is from an EXTERNAL source. Ensure you trust this sender (Email) before replying or clicking on any links and open attachments.

#### WITHOUT PREJUDICE

Dear Sir/Madam,

# ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS

We refer to your email of 17 May 2022 and thank you confirming your intention to conduct a pre-repair survey on our client's vehicle **SKD9900S**.

We have instructions to reject your surveyor and <u>propose to engage Nicky Seah (Absolute Appraisal Services</u>

<u>Pte Ltd)</u> from the workshop's list of surveyors.

Please be informed that the said <u>vehicle is not in workshop</u> yet. Kindly liaise with the workshop representatives accordingly:

Workshop: 833 Motorsports Pte Ltd

Address: 160 Sin Ming Drive #02-09 Autocity Building Singapore 575722

Contact Person: Mr Eldred (83322833)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

<sup>\*</sup>Please be in touch with the contact person for further arrangement.

For Surveyor: To initial after Completion

1st Inspection
Appointed surveyor
(Name & Siganature)

Date & Time

2nd Inspection
Appointed surveyor
(Name & Siganature)

Date & Time

3rd Inspection Appointed surveyor (Name & Siganature)

Date & Time

## Thank you.

From: Henry, Irene James < irene.henry@sompo.com.sg >

Sent: Tuesday, 17 May 2022 4:54 PM

To: SL LAW PRS <prs@sllaw.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: aaron tan <aarontkj.sk@gmail.com>

**Subject:** SOMPO REF:CMTD2201679/SYH/RE: URGENT ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS || PD.192604

Our Reference: CMTD2201679/SYH

Your Reference: PD.192604

**Without Prejudice** 

Date: 17.05.2022

#### Attention:

#### M/S SL LAW CHAMBERS

Dear Sirs.

# ACCIDENT INVOLVING <u>SKT 9012X</u> & SKD 9900S ON 12.05.2022

We refer to your Notice of Accident via email dated 17.05.2022.

Please be informed that Ms. Shiang Yi is the handler of this case who can be contacted at 6329 5205 / shiangyi.hwang@sompo.com.sg

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Salaction (Indicate as

			Selection (indicate as
	Motor Surveyor	Surveyor	tick)
		Kenneth Kong Seng	
1	LKK Auto Consultants	Cheong	
		Marcus Chua Kang Seng	
		Adrian Ling	
2	Priority Services	Jimmy Lee	
3	Raleigh Services	Andrew Ow Yong	
5	FormTeam Consultancy	Frankie Pang	
6	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert

Note: \* Currently working from home.

Best Regards Irene Henry Claims Division

D: 6322 4618 | T: 6461 6555



# Innovation for Wellbeing

#### Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <u>here</u> for our Privacy Policy.

From: SL LAW PRS prs@sllaw.com.sg>
Sent: Tuesday, May 17, 2022 4:10 PM

**To:** claimsreport < <u>claimsreport@sompo.com.sg</u>>; <u>Eldredgoh@gmail.com</u>; Claims - Motor Survey

<MotorSurvey@sompo.com.sg>

Cc: aaron tan <aarontki.sk@gmail.com>

Subject: URGENT ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY

BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS || PD.192604

**Importance:** High

CAUTION: This Email is from an EXTERNAL source. Ensure you trust this sender (Email) before replying or clicking on any links and open attachments.

#### WITHOUT PREJUDICE

Dear Sir/Madam,

# ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS

We are instructed to notify you of a road accident on 12 MAY 2022 at about 1606 HOURS ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) involving our client's vehicle registration number SKD9900S and vehicle registration number SKT9012X driven by your insured at the material time. A copy of the Accident Statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle is not in workshop yet. Kindly liaise with the workshop representatives accordingly:

Workshop: 833 Motorsports Pte Ltd

Address: 160 Sin Ming Drive #02-09 Autocity Building Singapore 575722

Contact Person: Mr Eldred (83322833)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

<sup>\*</sup>Please be in touch with the contact person for further arrangement.

For Surveyor: To initial after Completion

1st Inspection Appointed surveyor (Name & Siganature)

Date & Time

2<sup>nd</sup> Inspection Appointed surveyor (Name & Siganature)

Date & Time

3rd Inspection Appointed surveyor (Name & Siganature)

Date & Time

Thank you.

Regards Yuna

DID: 6909 9355 Fax: 6909 6246

Address: 133 New Bridge Road #13-01 Chinatown Point Singapore 059413



This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

From: SL LAW PRS

**Sent:** Tuesday, 17 May 2022 12:18 PM

To: claimsreport <claimsreport@sompo.com.sg>; Eldredgoh@gmail.com

Cc: aaron tan <aarontki.sk@gmail.com>

Subject: URGENT ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY

BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS || PD.192604

Importance: High

#### WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SKD9900S & SKT9012X ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) ON 12 MAY 2022 AT ABOUT 1606 HOURS

We are instructed to notify you of a road accident on 12 MAY 2022 at about 1606 HOURS ALONG CTE BRADDEL ROAD EXIT 10(SLIGHTLY BEFORE) involving our client's vehicle registration number SKD9900S and vehicle registration number SKT9012X driven by your insured at the material time. A copy of the Accident Statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle is not in workshop yet. Kindly liaise with the workshop representatives accordingly:

Workshop: 833 Motorsports Pte Ltd

Address: 160 Sin Ming Drive #02-09 Autocity Building Singapore 575722

Contact Person: Mr Eldred (83322833)

\*Please be in touch with the contact person for further arrangement.

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

For Surveyor: To initial after Completion

1st Inspection Appointed surveyor (Name & Siganature)

Date & Time

2<sup>nd</sup> Inspection Appointed surveyor (Name & Siganature)

Date & Time

3rd Inspection Appointed surveyor (Name & Siganature)

Date & Time

Thank you.

Regards Yuna

DID: 6909 9355

Fax: 6909 6246

Address: 133 New Bridge Road #13-01 Chinatown Point Singapore 059413

8

This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.