



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/ASM22004704/Tqy3e2 Date: 02/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8037G	Veh. Inspected	SNC 3336E
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M041A2	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	19/05/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLC250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WDC2533462F553943	Colour	WHITE
Odometer	32269 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/50 R19	MICHELIN	6 mm
L/H Front Tyre	255/50 R19	MICHELIN	6 mm
R/H Rear Tyre	255/50 R19	MICHELIN	6 mm
L/H Rear Tyre	255/50 R19	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/05/2022	Inspection Date	19/05/2022
Survey held at	1 KAKI BUKIT AVE 6 AUTOBAY @ KB #01-08		
Repairer	TSL AUTO GARAGE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	