

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 19/05/2022
To : UNITED OVERSEAS INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 17/01/2022

Vehicle No : GBF-5097-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	REAR BUMPER X R	667.20	
10	REAR BUMPER CLIPS X nn	50.00	
(2	TAILLAMP RH/LH - cut	494.60	247.30
1	TAILGATE - 09	1,986.70	
1	TAILGATE REAR VIEW MIRROR / RR (replaced already)	220.50	
1	TAILGATE LOCK X nn	297.50	
1	TAILGATE WEATHERSTRIPE X nn	154.50	
1	END PANEL X nn		
	RESTORE		

2207.20
- 10%
1986.48

2454.50
- 10%
2209.05

Date : 19/05/2022

To : UNITED OVERSEAS INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 17/01/2022

Vehicle No : GBF-5097-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	3871.00	
	Discount 10% On Parts	(387.10)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR X 1/1	220.00	
1	WINDSCREEN SEALANT / 1/1	40 / 50.00	
1	70KM/HR / 1/1	10.00	
1	8 PAX STICKER / 1/1	10.00	
1	REAR ADVERTISEMENT STICKER / 1/1 (bill)	400.00	
		460	

Date : 19/05/2022

To : UNITED OVERSEAS INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 17/01/2022

Vehicle No : GBF-5097-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	690.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	300 800.00	
	TO RESPRAY AFFECTED AREAS	400 800.00	
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	Sub Total	1750.00	850
	Remarks:		
	Steve (LKK) 19/5/22, 12.30h m n L/S M AL y 3 y s	= 3519.05 L/S - 2815.24 = 7800 5,923.90 L/S - 2637.18 = 2650	
	SUB TOTAL		
	GST 7.0 %	414.67	
	TOTAL	6,338.57	

Surveyor's name:

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE : 3