



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004707/Rvy3e2	
			Date: 29/09/2022	
			Code: AIS	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLK 6830G	Veh. Inspected	SJJ 3548X
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004866SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	19/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VIOS E AUTO	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053HY9305067874	Colour	WHITE
	Odometer	263582 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	ARIVO	6 mm
	L/H Front Tyre	195/55 R15	ARIVO	6 mm
	R/H Rear Tyre	195/55 R15	ARIVO	6 mm
	L/H Rear Tyre	195/55 R15	ARIVO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	13/05/2022	Inspection Date	19/05/2022
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	