

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22004709/KTY3N2
Date: 26/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001790964
Claimant Vehicle No :	SGG8984M	Insured Vehicle No :	GBB5319P
Date of Loss:	15/05/2022	Nature of Claim:	TP
		Claim No:	274535

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG8984M	Engine No:	3ZZ4559746
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053ZEC107117528
Reg. Date:	25/05/2006 (Man. Year: 2006)	Odometer:	101811 km
Colour:	Metallic Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,015.30	2,838.75	1,176.55	29.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,780.00	700.00	28.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,495.30	4,618.75	1,876.55	28.89
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	6,495.30	3,600.00	2,895.30	44.58

INSPECTION

Date of Assignment:	19/05/2022		
Date Inspected:	19/05/2022	Inspected At:	Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

FOR MANDATE ONLY

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2022)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG8984M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	667.70 FL	*667.70 FL
2	2		*BOOTLID HINGES	Bent	115.40 FL	*115.40 FL
3	1		*BOOTLID REFLECTOR	N/s Scratched	198.60 FL	*99.30 FL
4	1		*EMBLEM COROLLA	Necessary	32.30 FL	*32.30 FL
5	1		*EMBLEM ALTIS	Necessary	34.40 FL	*34.40 FL
6	1		*EMBLEM 1.6	Necessary	32.40 FL	*32.40 FL
7	1		*EMBLEM E	Necessary	38.20 FL	*38.20 FL
8	1		*BOOTLID CHROME	Cracked	125.80 FL	*125.80 FL
9	1		*BOOTLID UPPER LOCK	Dented	77.50 FL	*77.50 FL
10	1		*BOOTLID LOWER LOCK	Repair	29.90 FL	*- FL
11	2		*TAILLAMP	Cut / Mtg Cracked	563.20 FL	*563.20 FL
12	1		*END PANEL	Bent	700.30 FL	*644.80 FL
13	2		*TAILLAMP LOWER PANEL	N/s Buckled	172.80 FL	*172.80 FL
14	1		*END PANEL GARNISH	Distorted	93.30 FL	*93.30 FL
15	1		*REAR BUMPER	Bent	384.90 FL	*384.90 FL
16	2		*REAR BUMPER RETAINER	Distorted	37.60 FL	*37.60 FL
17	2		*REAR BUMPER BRACKET	Repair	97.00 FL	*- FL
18	1		*TAILLAMP CORNER PANEL	N/s Bent	759.80 FL	*294.00 FL
19	1		*SPARE TYRE PANEL	Repair	702.20 FL	*- FL
20	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
21	1		*BOOTLID RUBBER (50%)	Distorted/Cut	117.83 FS	*78.55 FS
					Sub Total (\$\$)	5,231.13 3,692.15
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,215.83 853.40
					Total Parts (\$\$)	4,015.30 2,838.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,000.00	900.00
3	WIRE CHECKING	New	80.00	20.00
4	TUFF KOTE	New	200.00	60.00
Gross Labour Cost (S\$)			2,480.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >