

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 27 May 2022

Preliminary Advice

Insured :
Vehicle No PC9519G,USEANOTHERFOLDER
TP Vehicle No : SGQ3375B
Make : HONDA STREAM
Date of Inspection : 19/05/2022
Inspection At : AUTOWORX HOUSE - SIN MING (HQ)
176 SIN MING DRIVE #02-01
SINGAPORE 575721

Accident Date : 17/05/2022
Assignment Date : 20/05/2022
Est. Duration of Repair : 9

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,403.92
Revised Amount	:S\$	5,874.60
Check Items (Estimated)	:S\$	5,921.52
Total	:S\$	11,796.12

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.