

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOW SOON HENG
BLK 605A TAMPINES ST 61 #08-302
SINGAPORE 521605

Contact : 85458867

TP chim.
Veron.

TAX INVOICE

Repair Code : CLM15530

Date in : 17/05/2022

Vehicle Num. : SMP5070B

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72007895/LEB7109878

Parts and Labour Assesment

Description of part	Qty	Unit Price	958 Amount
REAR BUMPER <i>Dehd.</i>	1	1350.60	1,350.60
REAR BUMPER REFLECTOR GARNISH L/R <i>LH cycled</i>	2	45.00	90.00
REAR BUMPER REFLECTOR L/R <i>LH cycled</i>	2	45.00	90.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	26.50	✓ 53.00
REAR BUMPER SPONGE L/R <i>LH cycled</i>	2	89.50	179.00
REAR BUMPER TOW HOOK COVER <i>new</i>	1	16.50	+ 16.50
REAR BUMPER UNDER COVER LH <i>new</i>	1	98.30	+ 98.30
REAR BUMPER UNDER COVER RH <i>new</i>	1	95.20	+ 95.20
REAR END PANEL <i>Dehd.</i>	1	560.80	✓ 560.80
REAR END PANEL INNER TOP GARNISH <i>Dehd.</i>	1	155.50	✓ 155.50
REAR TAILGATE <i>Dehd.</i>	1	1193.00	✓ 1,193.00
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	75.80	✓ 75.80
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	38.00	+ 38.00
REAR TAILGATE 'SHUTTLE' EMBLEM <i>new</i>	1	55.00	✓ 55.00
REAR TAILGATE HINGES L/R <i>new</i>	2	50.00	+ 100.00
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	25.00	+ 25.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	18.50	+ 37.00
REAR TAILGATE INNER TRIM BOARD <i>cycled</i>	1	320.00	✓ 320.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LOW SOON HENG
 BLK 605A TAMPINES ST 61 #08-302
 SINGAPORE 521605

Contact : 85458867

TAX INVOICE

Repair Code : CLM15530

Date in : 17/05/2022

Vehicle Num. : SMP5070B

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72007895/LEB7109878

REAR TAILGATE LOCK STRIKER <i>new</i>	1	27.50	+	27.50
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	157.10	✓	157.10
REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH <i>new</i>	1	383.10	+	383.10
REAR TAILGATE OUTER LOCK OPENER SWITCH <i>new</i>	1	175.50	+	175.50
REAR TAILGATE REFLECTOR INNER RUBBER GASKET L/R <i>new</i>	2	25.00	✓	50.00
REAR TAILGATE REFLECTOR L/R <i>combined</i>	2	395.00	✓	790.00
REAR TAILGATE WEATHER STRIP <i>new</i>	1	168.50	✓	168.50
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	120.00	✓	120.00
REAR TAILLAMP L/R <i>combined</i>	2	520.50	✓	1,041.00
Subtotal before discount				7,445.40
Percentage discount 20%				1,489.08
Sub-total 1				5,956.32
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00
REAR BUMPER REVERSE SENSOR <i>new</i>	1	280.00	20	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	50.00	10	50.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	40.00	30	40.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOW SOON HENG
BLK 605A TAMPINES ST 61 #08-302
SINGAPORE 521605

Contact : 85458867

TAX INVOICE

Repair Code : CLM15530

Date in : 17/05/2022

Vehicle Num. : SMP5070B

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72007895/LEB7109878

REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00
REAR TAILLAMP CLIPS L/R - SET	2	15.00	30.00
Subtotal before discount			665.00
Percentage discount 0%			0.00
Sub-total 2			665.00
Parts-total			6,621.32

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,530.00
Parts & Labour Total	9,151.32

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

total: 7051.76

2/s: 5.6K ✓