

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22004722/GQY3E2

Date: 10/06/2022

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW005711		
Claimant Vehicle No :	SH9657D	Insured Vehicle No :	SKN5870T		
Date of Loss:	15/05/2022	Nature of Claim:	TP	Claim No:	M2202466

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9657D		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU299285
Reg. Date:	06/08/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU165109
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,051.52	1,377.12	2,674.40	66.01
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,062.52	1,388.12	2,674.40	65.83
+ GST 7.00/7.00% (S\$)	284.38	97.17	187.21	65.83
Nett Amount (S\$)	4,346.90	1,485.29	2,861.61	65.83

INSPECTION

Date of Assignment:	19/05/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	19/05/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9657D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	-	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
3	1		*REAR FENDER RH	Repair	1,768.30 FL	-	*- FL
4	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	-	*- FL
5	1		*RR WHEEL HUB CAP RH	Scratched	346.40 FL	-	*346.40 FL
6	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	-	*50.00 F
7	1		*RR FENDER ADVERTISEMENT STICKER RH	Necessary	100.00 F	-	*100.00 F
8	1		*RR FENDER ADVERTISEMENT STICKER LH	Necessary	100.00 F	-	*100.00 F
9	1		*PANEL BEATING		900.00 F	-	*350.00 F
10	1		*SPRAY PAINTING CHARGE		600.00 F	-	*500.00 F
11	1		*TUFF KOTE		60.00 F	-	*- F
12	1		*REMOVE/ REFIX UPHOLSTERY & CUSHION RR		120.00 F	-	*- F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,581.90	1,446.40
- List Item Discount on L Items 20.00/20.00% (\$)	530.38	69.28
Total Parts (\$)	4,051.52	1,377.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >