

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SKF 4378 Y**

Model : TOYOTA RAIZE

Year : 2020

Chassis No : A200A0081378

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	TAILGATE	1	\$ (1850) 2,850.00	\$ 2,850.00
2	TAILGATE EMBLEM 'RAIZE'	1	\$ 58 84.00	\$ 84.00
3	TAILGATE INNER TRIM BOARD	1	\$ X 584.10	\$ 584.10
4	TAILGATE LAMP	2	\$ X 581.60	\$ 1,163.20
5	TAILGATE WLATHERSTRIP	1	\$ 355 382.60	\$ 382.60
6	TAILGATE INNER LOCK	1	\$ 390 625.00	\$ 625.00
7	TAILGATE LOCK STRIKER	1	\$ X 58.00	\$ 58.00
8	TAILGATE ANTENNA SENSOR	1	\$ X 186.00	\$ 186.00
9	TAILGATE WINDSCREEN MOULDING	1	\$ (XNF) 387.20	\$ 387.20
10	REAR BUMPER <i>upper</i>	1	\$ 1245 1,920.00	\$ 1,920.00
11	REAR BUMPER LOWER	1	\$ 652 750.00	\$ 750.00
12	REAR BUMPER SIDE RETAINER	2	\$ - 98.20	\$ 196.40
13	REAR BUMPER REFLECTOR	2	\$ X 125.00	\$ 250.00
14	REAR BUMPER LOWER BRACKET	2	\$ X 171.45	\$ 342.90
15	REAR BUMPER SIDE COVER GARNISH	2	\$ X 260.00	\$ 520.00
16	REAR END PANEL INNER	1	\$ X 780.00	\$ 780.00
17	REAR END PANEL OUTER	1	\$ 440 691.60	\$ 691.60
18	REAR END PANEL TOP GARNISH	1	\$ X 389.00	\$ 389.00
19	REAR END PANEL AIR VENTS	1	\$ - 85.70	\$ 85.70
20	TAILLAMP	2	\$ X 682.10	\$ 1,364.20
21	TAILLAMP LOWER BRACKET	2	\$ X 84.00	\$ 168.00
Parts Sub Total :				\$ 13,777.90
Discount 25% :				\$ 3,444.48
PARTS TOTAL :				\$ 10,333.43

BR
NCN
ND
NDX
TNV
JMV
ND
NDX
NEC
BRV
BRV
NEC
ND
NDX
DD
NDX
BRV
NEC
X

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	SUNDRIES	1	\$ 80.00	\$ -80.00	NN
2	TAILGATE OUTER GARNISH CLIPS	1	\$ 50.00	\$ 20.00 50.00	NE
3	TAILGATE INNER TRIM BOARD CLIPS	1	\$ 50.00	\$ 50.00	NN
4	TAILGATE LAMP SEAL	2	\$ 60.00	\$ 120.00	NN
5	TAILGATE LAMP CLIPS	2	\$ 50.00	\$ 40.00 100.00	NE
6	TAILGATE WINDSCREEN CLIPS	1	\$ 50.00	\$ 50.00	NS
7	TAILGATE WINDSCREEN SEALANT	1	\$ 120.00	\$ 40.00 120.00	NE
8	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	NN
9	TAILGATE WINDSCREEN PRIMER AND CLEANER	1	\$ 100.00	\$ 100.00	NN
10	REAR BUMPER CLIPS	1	\$ 50.00	\$ 30.00 50.00	NN
11	REAR BUMPER LOWER CLIPS	1	\$ 50.00	\$ 30.00 50.00	NN
12	REAR BUMPER SIDE COVER GARNISH CLIPS	1	\$ 50.00	\$ 50.00	NN
13	REAR BUMPER REVERSE SENSOR	2	\$ 250.00	\$ 200.00 500.00	NN
14	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00	NN
15	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 50.00	NN
16	TAIL LAMP SEAL	2	\$ 60.00	\$ 120.00	NN
17	TAIL LAMP CLIPS	2	\$ 50.00	\$ 100.00	NN
SPECIAL NETT TOTAL :				\$ 1,750.00	

Nos.	LABOUR	S\$	
1	R&R TAILGATE COMPONENT	\$ 80.00 150.00	✓
2	R&R TAILGATE WINDSCREEN	\$ 120.00 300.00	✓
3	R&R REAR BUMPER REVERSE SENSOR	\$ 60.00 100.00	✓
4	CHECK WIRING	\$ 20.00	NN
5	UPHOLSTERY	\$ 300.00	NN
6	PANEL BEATING	\$ 800.00 1,600.00	✓
7	RUST PROOFING	\$ 200.00	NNX
8	SPRAY PAINTING	\$ 600.00 1,600.00	✓
LABOUR TOTAL :		\$ 4,410.00	

survey 19/5/2022
 Resurvey 20/5/2022
 Tt in hr 12.45 hrs
 Tt in hr 11.30 hrs

Lump sum repair
 Repair days 6

PARTS TOTAL : \$ 10,333.43
 SPECIAL NETT TOTAL : \$ 1,750.00
 LABOUR TOTAL : \$ 4,410.00
GRAND TOTAL : \$ 16,493.43

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: