

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAI	NCE BHD	R	Ref:	CS3/LPC22004728/Gqy3	
	300 BEACH ROAD #17-04/07 THE CC	) NCOURSESINGAPORE 199555	D	Date:	19/05/2022	
			C	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBB 4193R	Veh. Inspected		SKB 896R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/025804	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		19/05/2022	
2.	Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	5. General Information					
	Accident Date	12/05/2022	Inspection Date		20/05/2022	
	Survey held at					
	68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB SINGAPORE 417896					
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					