

CS/CI 2004729/1 Bv3

boc TR

DLRR

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

All Seng
Wong

Repair Estimate

Vehicle number: GBC5490X

Make & Model: Toyota Dyna

Chassis number: JTFAT35Y30K202161

Date of survey: _____

Name of surveyor: _____

Contacts: _____

No.	Description of spare parts	Qty	Amount S\$	
1	Front bumper	1	\$ 651.00	BT ✓
2	Front bumper LH bracket	1	\$ 121 ✓ 212.00	BT ✓
3	Front grille	1	\$ 567.00	BR ✓
4	Front grille emblem	1	\$ 75.00	NE ✓
5	Front grille clips	1set	\$ 30.00 ✓ 50.00	NE ✓
6	LH headlamp assy	1	\$ 978.00	CU ✓
7	LH headlamp lock clips	1set	\$ 20.00 ✓ 32.00	NE ✓
8	Front panel	1	\$ 1,019.00	ND ✓
9	Front panel "Dyna" emblem	1	\$ 93.00	NN ✓
10	Front LH corner panel	1	\$ 264 ✓ 442.00	DD ✓
11	Front LH corner panel upper garnish	1	\$ 193.00	NN ✓
12	Front LH corner panel upper garnish clips	1set	\$ 30.00	NN ✓
13	LH side mirror arm	1	\$ 683.00	
14	LH side round mirror	1	\$ 189.00	
15	LH side rectangle mirror	1	\$ 412.00	ND ✓
16	LH front door	1	\$ 1485 ✓ 1,776.00	DD ✓
17	LH front door upper hinge	1	\$ 116.00	ND ✓
18	LH front door lower hinge	1	\$ 116.00	BT ✓
19	LH front door checker	1	\$ 132.00	NN ✓
20	LH front door inner trim board	1	\$ 551.00	? BR ✓
21	LH front door inner trim board clips	1set	\$ 30.00 ✓ 50.00	NE ✓
22	LH front door glass regulator gear	1	\$ 376.00	BT ✓
23	LH front door glass regulator gear motor	1	\$ 448.00	ND ✓
24	LH front door lock	1	\$ 354.00	ND ✓
25	LH front door pillar	1	\$ 876.00	?
26	LH front door pillar rubber seal	1	\$ 281.00	? ND ✓
27	LH front door quarter garnish	1	\$ 113.00	ND ✓
28	LH front door speaker	1	\$ 221.00	ND ✓
29	LH front door weatherstrip	1	\$ 363.00	
30	LH front door lower rubber seal	1	\$ 94.00	
31	LH front step garnish	1	\$ 312.00	
32	LH front step garnish panel	1	\$ 274.00	? ND ✓
33	LH front arch panel	1	\$ 391.00	
34	LH front arch panel garnish	1	\$ 287.00	
35	LH front arch panel garnish clips	1set	\$ 35.00	
36	Dashboard	1	\$ 972.00	ND ✓
37	LH front lower arm	1	\$ 1,029.00	ND ✓

38	LH front lower arm ball joint	1	\$	562.00
39	LH front shock absorber	1	\$	364.00
40	LH front knuckle arm	1	\$	1,248.00
41	LH front wheel bearing	1	\$	312.00
42	LH front mudguard	1	\$	317.00

NDX

Parts less 25% \$ 17,596.00
 Total \$ 4,399.00
 Total \$ 13,197.00

5264
 -25%
 3948

No.	Special Nett Items		Amount S\$
1	LH front door company detail sticker	1	\$20.00 ✓ 40.00
2	LH front door pillar seal	1	\$ 70.00
3	Front number plate	1	\$ 40.00 ✓ 20.00
4	LH front rim	1	\$ 550.00
5	LH front tyre	1	\$ 300.00
6	Brake fluid	1	\$ 70.00

NEC ✓
 ?NNX
 BT ✓
 NNX

Total: \$ 1,100.00

60

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 800.00 1,800.00
2	Spray painting on affected areas and panels	\$ 700.00 1,500.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Remove and reinstall dashboard and all dashboard attachments to carry repair	\$ 300.00
6	Refocus and adjust headlamps assy	\$ 80.00
7	Remove and replace front LH door inner mechanism to carry repair	\$ 80.00 120.00
8	Remove and reinstall aircon blower and heater to carry repair. To refill gas	\$ 320.00
9	Remove, reinstall and replace front LH inner trims, garnish and seat to carry repair	\$ 280.00
10	Adjust and test drive wheel alignment	\$ 100.00
11	Remove and replace front undercarriage parts	\$ 380.00

NNX

NNX

NNX

Total: \$ 5,080.00

1580

5588

L/S - 4470.40
 = 4450

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 13,197.00

Special Nett: \$ 1,100.00

Labour: \$ 5,080.00

Total Amount: \$ 19,377.00

Survey + Resurvey

20/5/2022

Tellin Lin

14 10 hrs

Lump sum repair

Repair days 9

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: