



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22004730/Vny3m4 Date: 10/08/2022 Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YQ 293K
	Policy No.	001402 (COVER NOTE)	Coverage (\$)	0.00
	Claim No.	D22001487MFCV	Excess (\$)	2,000.00
	Assign From	HARMINDER KAUR	Assign Date	19/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ SPRINTER	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDB9062532N773769	Colour	MIX
	Odometer	36751 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/75 R16	DURATURN	5 mm
	L/H Front Tyre	205/75 R16	DURATURN	5 mm
	R/H Rear Tyre	205/75 R16	DURATURN	5 mm
	L/H Rear Tyre	205/75 R16	DURATURN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/05/2022	Inspection Date	19/05/2022
	Survey held at	Blk 3011 BEDOK industrial park E #01-2000.		
	Repairer	KING AUTO SUPPLIES		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$60,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	