



King Auto Technologies & Engineering Pte Ltd

Blk 3011 Bedok Industrial Park E #01-2000 Singapore 489977

Telephone : 91250481 Facsimile : 67814547

Estimated repair of YQ 293 K

Date : 2-Jun-2022
 Name : SBS Transit Ltd
 Address : c/o Block 3011, Bedok North Avenue 4
 #01-2000 / 2002 Bedok Industrial Park E
 Singapore 489977
 Model : Mercedes Sprinter
 Accident Date : 11-May-2022

Serial No.	Descriptions	Amount (S\$)
------------	--------------	--------------

Nett Items

1	Front Grille	\$ 916.00	scr
1	Front grille logo	\$ 180.00	scr
1	Front headlamp	\$ 2,200.00	scr
1	Front support panel	\$ 2,160.00	scr
1	Front bumper	\$ 1,983.00	scr
1	Front bumper reinforcement	\$ 1,895.00	scr
1	Dust pot	\$ 201.00	scr
		\$ 9,535.00	
	Less 10.0%	\$ 953.50	
		\$ 8,581.50	

S/N

Labour

1	To remove and refit front headlamps wiring.	\$ 50.00	30
2	To remove and refit air-con condenser.	\$ 180.00	xnn
3	To remove and refit radiator.	\$ 120.00	xnn
4	To remove, refit and repair all the above parts.	\$ 1,000.00	400
7	To spray paint on the replacement and repair parts.	\$ 800.00	400
		\$ 2,150.00	

Grand - total : \$ 10,731.50

Dollar : Ten Thousand Seven Hundred Thirty One and Fifty Only

Thuan

82235769

7/6/22 1700

P/P htr paint photo

3days wp

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: