



# King Auto Technologies & Engineering Pte Ltd

Blk 3011 Bedok Industrial Park E #01-2000 Singapore 489977

Telephone : 91250481 Facsimile : 67814547

## Estimated repair of YQ 293 K

Date : 2-Jun-2022  
 Name : SBS Transit Ltd  
 Address : c/o Block 3011, Bedok North Avenue 4  
 #01-2000 / 2002 Bedok Industrial Park E  
 Singapore 489977  
 Model : Mercedes Sprinter  
 Accident Date : 11-May-2022

Serial No.	Descriptions	Amount (S\$)
------------	--------------	--------------

	<u>Nett Items</u>	
1	Front Grille	\$ 916.00 /scr
1	Front grille logo	\$ 180.00 XSVL
1	Front headlamp	\$ 1050 2,200.00 /crv
1	Front support panel	\$ 475 2,160.00 Xr/BV
1	Front bumper	\$ 990 1,983.00 -DT
1	Front bumper reinforcement	\$ 850 1,895.00 Xr/DT
1	Dast pot	\$ 201.00 /scr
		\$ 9,535.00
	Less 10.0%	\$ 953.50
		\$ 8,581.50

<u>S/N</u>	<u>Labour</u>	
1	To remove and refit front headlamps wiring.	\$ 50.00 30
2	To remove and refit air-con condenser.	\$ 180.00 Xrv
3	To remove and refit radiator.	\$ 120.00 Xrv
4	To remove, refit and repair all the above parts.	\$ 1,000.00 400
7	To spray paint on the replacement and repair parts.	\$ 800.00 400
		\$ 2,150.00

Grand - total : \$ 10,731.50

Dollar : Ten Thousand Seven Hundred Thirty One And Cents Fifty Only

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5  
 F: 3900  
 RP: 4

Thuan  
 82235769  
 7/6/22 1700  
 P/P btr paint photo  
 3days w/p