

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ADRIAN NG CHING FOO
 BLK 482 PASIR RIS DRIVE 4 #11-385
 SINGAPORE 510482

Contact : 90291975

*TP Budget Direct
 Veron*

TAX INVOICE

Repair Code : CLM15531

Date in : 14/05/2022

Vehicle Num. : SMD889C

Model : MERCEDES BENZ C 200 KOMPRESSOR

Chassis/Eng# : WDD2040412A053286/27195030955783

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID LOGO <i>Neu</i>	1	53.60	✓ 53.60
REAR BOOTLID LOGO CLIPS <i>Neu</i>	3	6.50	✓ 19.50
REAR BUMPER CENTER GUIDE BRACKET <i>could</i>	1	163.00	✓ 163.00
REAR BUMPER LOWER BRACKET L/R <i>Delhd</i>	2	65.70	✓ 131.40
REAR BUMPER REINFORCEMENT <i>Detekt</i>	1	624.00	✓ 624.00
REAR BUMPER REVERSE SENSOR <i>Dungd</i>	2	258.10	✓ 516.20
REAR BUMPER REVERSE SENSOR 'O' RING <i>Neu</i>	2	9.80	✓ 19.60
REAR BUMPER REVERSE SENSOR HOLDER BRACKET <i>Neu</i>	4	38.00	✓ 152.00
REAR END PANEL <i>Ryrt</i>	1	1362.00	✗ 1,362.00
REAR TAILLAMP L/R <i>Neu</i>	2	679.52	✗ 1,359.04
REAR TAILLAMP LOWER BRACKET L/R <i>could</i>	2	75.00	✓ 150.00
Subtotal before discount			4,550.34
Percentage discount 10%			455.03
Sub-total 1			4,095.31
REAR BUMPER (AMG) <i>Delhd</i>	1	2600.00	<i>chw</i> 2,600.00
REAR BUMPER CLIPS - SET <i>Neu</i>	1	50.00	✓ 50.00
REAR BUMPER LOWER LID (AMG) <i>could</i>	1	800.00	<i>500</i> 800.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Neu</i>	1	30.00	✗ 30.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ADRIAN NG CHING FOO
 BLK 482 PASIR RIS DRIVE 4 #11-385
 SINGAPORE 510482

TAX INVOICE

Repair Code : CLM15531
 Date in : 14/05/2022
 Vehicle Num. : SMD889C
 Model : MERCEDES BENZ C 200 KOMPRESSOR
 Chassis/Eng# : WDD2040412A053286/27195030955783

Contact : 90291975

REAR END PANEL SEALANT	1	100.00	+ 100.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	+ 60.00
Subtotal before discount			3,640.00
Percentage discount 0%			0.00
Sub-total 2			3,640.00
Parts-total			7,735.31

LABOUR

To reset system after repair works	+ 250.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓ 60.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	GW 1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	500 1,000.00
To apply anti-rust chemical on repaired and replaced panel.	✓ 50.00
Labour Total	2,700.00
Parts & Labour Total	10,435.31

1270

*** This is a computer-generated document which requires no signature.***

page 2

Adrian Ng
 A/S 23/05/22

04 Days

total: 5266.37

A/S: 4.2K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: