

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 28 Jun 2022

Preliminary Advice

Insured : SMM6635G

Vehicle No

TP Vehicle : SMR2757M
No

Accident Date : 17/05/2022

Make : TOYOTA CAMRY

Assignment Date : 19/05/2022

Date of : 20/05/2022

Est. Duration of : 7
Repair

Inspection

Inspection At : SIN MING AUTOCARE BFG PTE LTD (HQ)
176, SIN MING DRIVE #02-05, SIN MING AUTOCARE
COMPLEX
SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 27,590.93

Revised Amount :S\$ 19,205.43

Check Items (Estimated) :S\$ 0.00

Total :S\$ 19,205.43

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.