



ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600
Attn: Motor Claim Dept

CHASSIS: MR2B63HK304004074

Sin Ming Autocare BFG Pte Ltd
176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 I Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

Not Authorized
Runway B4pam
Today
@19,205.43

ESTIMATE

VEHICLE NO: SMR2757M
MAKE/MODEL: TOYOTA CAMRY
DATE: 18.05.2022

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:				
1	BOOTLID → 1572.80	1	1,576.90	1,576.90 ✓
2	BOOT HINGE RH	1	228.00	R 228.00 X
3	BOOT HINGE LH	1	228.00	R 228.00 X
4	BOOT LIDE HINGE COVER LH	1	85.60	Sn 85.60 X
5	BOOT LIDE HINGE COVER RH	1	85.60	Sn 85.60 X
6	BOOT LID WEATHERSTRIP	1	284.70	DIY 100 284.70 ✓
7	BOOT LOCK	1	423.90	R 423.90 X
8	BOOT OUTER MOULDING	1	245.10	Sn 245.10 X
9	BOOT EMLEM LOGO	1	85.60	Sn 85.60 ✓
10	BOOT EMBLEM 'CAMRY'	1	108.15	an 108.15 X
11	BOOT EMBLEM '2.5'	1	77.10	an 77.10 ✓
12	BOOT INNER TRIM	1	795.50	Sn 795.50 X
13	BOOT INNER TRIM CLIP	20	4.50	an 90.00 X
14	TAIL LAMP RH → 908.30	1	914.25	an 914.25 ✓
15	TAIL LAMP LH → 908.30	1	914.25	an 914.25 ✓
16	TAIL LAMP PANEL RH	1	282.70	R 282.70 X
17	TAIL LAMP PANEL LH	1	282.70	R 282.70 X
18	SPARE WHEEL PANEL	1	996.90	R 996.90 X
19	SPARE WHEEL PANEL COVER	1	589.80	DIY 589.80 ✓
20	REAR BODY PANEL → 892.35	1	896.61	R 896.61 ✓
21	REAR BODY PANEL TOP GARNISH	1	334.20	DIY 334.20 ✓
22	REAR FENDER INNER TRIM LH	1	481.60	Sn 481.60 X
23	REAR FENDER INNER TRIM RH	1	481.60	Sn 481.60 X
24	REAR BUMPER	1	678.80	R 678.80 ✓
25	REAR BUMPER BRACKET	1	85.60	R 85.60 X
26	REAR BUMPER SIDE RETAINER LH	1	131.80	Sn 131.80 X
27	REAR BUMPER SIDE RETAINER RH	1	131.80	Sn 131.80 X
28	REAR EXHAUST MUFFLER	1	1,073.80	R 1,073.80 X
29	REAR TAIL LAMP SIDE COVER LH	1	75.10	Sn 75.10 X
30	REAR TAIL LAMP SIDE COVER RH	1	75.10	Sn 75.10 X
31	REAR BUMPER REFLECTOR RH	1	86.50	Sn 86.50 X
32	REAR BUMPER REFLECTOR LH	1	86.50	Sn 86.50 X
33	REAR BUMPER LOWER GARNISH	1	542.10	Sn 542.10 ✓
34	REAR BAZER SENSOR	1	198.50	Sn 198.50 X
35	REAR REVERSE SENSOR WIRE	1	385.10	Sn 385.10 X
36	REAR TOOL BOX	1	198.70	Sn 198.70 X
37	REAR TOOL BOX TRAY	1	215.25	DIY 215.25 ✓ 482.49

**Sin Ming Autocare BFG Pte Ltd**

176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 | Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600
Attn: Motor Claim Dept

CHASSIS: MR2B63HK304004074

ESTIMATE

VEHICLE NO: **SMR2757M**
MAKE/MODEL: **TOYOTA CAMRY**
DATE: **18.05.2022**

38	REAR BUMPER REINFORCEMENT	1	382.20	B	382.20	✓
39	FRONT BUMPER <i>801.90</i>	1	838.40	Bu	838.40	✓
40	FRONT BUMPER CENTER GRILLE	1	760.50	cm	760.50	✓
41	FRONT BUMPER TOP RUBBER	1	117.15	ru	117.15	✓
42	FRONT BUMPER CENTER GRILLE BASE	1	245.15	cm	245.15	✓
43	FRONT GRILLE	1	450.10	cat	450.10	✓
44	FRONT GRILLE LOGO <i>1072.20</i>	1	1,091.60	gr	1,091.60	✓
45	FRONT HEADLAMP RH <i>→ 4614.80</i>	1	4,635.90	mgcm	4,635.90	✓
46	FRONT HEADLAMP LH <i>4614.80</i>	1	4,635.90	h	4,635.90	✓
47	FRONT SUPPORT PANEL TOP GARNISH	1	248.20	su	248.20	×
48	TOWING COVER	1	38.15	ru	38.15	×
			Sub Total (S\$) :		27,896.66	
			Discount (25%) :		6,974.17	
			Total Parts (S\$) :		<u>20,922.50</u>	

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	1	50.00	nd	50.00	} 45.00
2	FRONT NUMBER PLATE HOLDER	1	30.00		30.00	
3	REAR NUMBER PLATE	1	50.00	su	50.00	×
4	REAR NUMBER PLATE HOLDER	1	30.00	su	30.00	×
5	REAR REVERSE SENSOR CENTER RH <i>301.80 → 259</i>	1	392.80	short	392.80	✓
6	REAR REVERSE SENSOR CENTER LH	1	392.80	su	392.80	×
7	REAR CAMERA	1	480.00	su	480.00	×
			Sub Total (S\$) :	<u>1,425.60</u>	<u>1,425.60</u>	

LABOUR:

1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT ON AFFECTED AREAS.	2,500.00	<i>800</i>
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON EFFECTED	1,800.00	<i>1500</i>
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	200.00	<i>80</i>
4	LABOUR TO REMOVE AND REPLACE REAR BOOTLID.	200.00	<i>50</i>
5	TO CHECK WIRING FUNCTIONS.	80.00	<i>40</i>

Total Labour (S\$) :

4,780.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25,702.50

for Sin Ming Autocare BFG Pte Ltd



Sin Ming Autocare BFG Pte Ltd
176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 | Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600
Attn: Motor Claim Dept

CHASSIS: MR2B63HK304004074

ESTIMATE

VEHICLE NO: SMR2757M
MAKE/MODEL: TOYOTA CAMRY
DATE: 18.05.2022

SUPPLEMENTARY

lo. Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:			
1 FRONT BUMPER SPONGE	1	158.15	Sm 158.15 X
2 FRONT RADIATOR SIDE GARNISH RH	1	109.20	Dir 109.20 ✓
3 FRONT RADIATOR SIDE GARNISH LH	1	109.20	cm 109.20 ✓
1 FRONT BUMPER NUMBER BASE	1	124.80	cm 124.80 ✓
6 REAR COMPARTMENT LOWER COVER	1	894.06	cm 894.06 ✓
7 REAR TOOL BOX TRAY	1	482.49	482.49 ✓ <i>piece and</i>
Sub Total (S\$):			1,877.90
Discount (25%):			469.48
Total Parts (S\$):			1,408.43

LABOUR:

OBN DIAGNOSTIC

480.00

20%


Total Labour (S\$):

1,888.43

Total Amount (S\$):

1,888.43

81127.95



for Sin Ming Autocare BFG Pte Ltd