

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 17.05.22

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLQ7200L
MODEL : SUZUKI VITARA
DATE OF ACCIDENT : 17.05.22
TIME OF ACCIDENT : 11:50HRS

TSMLYD21S00201334.
Ashes.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 1,165.00	\$ 1,165.00
2	REAR BUMPER (LOWER)	1	\$ 338.00	\$ 338.00
3	REAR BUMPER REFLECTOR <i>Crushed</i>	2	\$ 21.00	\$ 42.00
4	REAR BUMPER LAMP <i>Missing</i>	1	\$ 48.00	\$ 48.00
5	REAR BUMPER TOWING COVER <i>New</i>	1	\$ 54.00	\$ 54.00
6	REAR BUMPER SIDE RETAINER <i>Ne</i>	2	\$ 26.00	\$ 52.00
7	REAR BUMPER REVERSE SENSOR <i>Spoke</i>	4	\$ 132.00	\$ 528.00
8	REAR BUMPER REINFORCEMENT <i>Dented</i>	2	\$ 271.00	\$ 542.00
9	REAR BUMPER INNER SIDE GARNISH <i>New</i>	2	\$ 104.00	\$ 208.00
10	REAR BUMPER SENSOR WIRE HARNESS <i>Not shipped</i>	1	\$ 180.00	\$ 180.00
11	REAR BUMPER REVERSE SENSOR HOLDER <i>Ne</i>	4	\$ 114.00	\$ 456.00
12	REAR FENDER INNER COWLING <i>New</i>	2	\$ 174.00	\$ 348.00
13	REAR FENDER ARCED GARNISH <i>Crushed</i>	2	\$ 106.00	\$ 212.00
14	REAR FENDER INNER TRIM <i>Crushed</i>	2	\$ 480.00	\$ 960.00
15	TAIL LAMP <i>Crushed</i>	2	\$ 434.00	\$ 868.00
16	TAILGATE <i>Distorted</i>	1	\$ 1,204.00	\$ 1,204.00
17	TAILGATE LAMP <i>Crushed</i>	2	\$ 300.00	\$ 600.00
18	TAILGATE EMBLEM 'SUZUKI' <i>3 New</i>	1	\$ 26.00	\$ 26.00
19	TAILGATE EMBLEM 'VITARA'	1	\$ 37.00	\$ 37.00
20	TAILGATE NUMBER PLATE LAMP <i>New</i>	2	\$ 30.00	\$ 60.00
21	TAILGATE OUTER MOULDING <i>Crushed</i>	1	\$ 385.00	\$ 385.00
22	TAILGATE DAMPER <i>Not ne</i>	2	\$ 124.00	\$ 248.00
23	TAILGATE HINGE <i>Not ne</i>	2	\$ 78.00	\$ 156.00
24	TAILGATE SWITCH BUTTOM	1	\$ 144.00	\$ 144.00
25	TAILGATE LOCK CATCH <i>Ne</i>	1	\$ 198.00	\$ 198.00
26	TAILGATE INNER HOLDER <i>Ne</i>	1	\$ 54.00	\$ 54.00

871

264.

271.

100.

724.

1043.

510.

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLQ7200L
 MODEL : SUZUKI VITARA
 DATE OF ACCIDENT : 17.05.22
 TIME OF ACCIDENT : 11:50HRS

27	TAILGATE INNER LOCK <i>Dehd</i>	1	\$ 198.00	\$ 198.00	✓
28	TAILGATE LOCK DETECTOR <i>Dehd</i>	1	\$ 132.00	\$ 132.00	✓
29	TAILGATE INNER TRIM BOARD <i>Dehd</i>	1	\$ 391.00	\$ 391.00	✓
30	TAILGATE WEATHER STRIP <i>ht</i>	1	\$ 172.00	\$ 172.00	✓
31	TAILGATE WIPER ARM <i>ht</i>	1	\$ 56.00	\$ 56.00	✓
32	TAILGATE WIPER MOTOR <i>Dehd</i>	1	\$ 372.00	\$ 372.00	✓
33	TAILGATE WIPER MOTOR HEAD COVER <i>ht</i>	1	\$ 30.00	\$ 30.00	✓
34	TAILGATE WINDSCREEN C/W MOULDING <i>ht</i>	1	\$ 132.00	\$ 132.00	✓
35	REAR END PANEL <i>Dehd</i>	1	\$ 496.00	\$ 496.00	✓
36	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 180.00	\$ 180.00	✓
37	REAR AIR VENT <i>Dehd</i>	2	\$ 37.00	\$ 74.00	✓
38	REAR TOOLS COMPARTMENT COVER BOARD (UPPER) <i>Dehd</i>	1	\$ 192	\$ 192	✓
39	REAR TOOLS COMPARTMENT COVER BOARD (LOWER) <i>Dehd</i>	1	\$ 224	\$ 224	✓

88802
 7481.70
 7209.20

TOTAL PRICE \$ 11,022.00
 LESS 10% 15% \$ 1,102.20
 SUB TOTAL PRICE \$ 9,919.80

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	50
2	REAR BUMPER CLIP (SET) <i>ht</i>	1	\$ 80.00	\$ 80.00	30
3	TAILLAMP CLIP (SET) <i>ht</i>	1	\$ 30.00	\$ 30.00	20
4	REAR FENDER INNER TRIM CLIP (SET) <i>ht</i>	1	\$ 80.00	\$ 80.00	60
5	REAR FENDER INNER COWLING CLIP (SET) <i>ht</i>	1	\$ 80.00	\$ 80.00	+
6	REAR FENDER ARCED GARNISH CLIP (SET) <i>ht</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE OUTER MOULDING CLIP (SET) <i>ht</i>	1	\$ 60.00	\$ 60.00	20
8	TAILGATE INNER TRIM BOARD CLIP (SET) <i>ht</i>	1	\$ 80.00	\$ 80.00	30
9	TAILGATE WINDSCREEN SEALANT <i>2</i>	1	\$ 80.00	\$ 80.00	40
10	TAILGATE WINDSCREEN INNER SEAL <i>ht</i>	1	\$ 60.00	\$ 60.00	30
11	REAR END PANEL INSULATION SEAL <i>ht</i>	1	\$ 150.00	\$ 150.00	60
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>ht</i>	1	\$ 40.00	\$ 40.00	20

TOTAL \$ 900.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	900
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	800

400

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ7200L**
 MODEL : **SUZUKI VITARA**
 DATE OF ACCIDENT : 17.05.22
 TIME OF ACCIDENT : 11:50HRS

3	TUFF COAT	\$ 250.00	60
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
5	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
6	REMOVE AND REFIX TAIL GATE WINDSCREEN	\$ 120.00	✓
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 150.00	50
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2120

TOTAL \$ 3,630.00

TOTAL PARTS COST : \$ 10,819.80
 TOTAL LABOUR COST : \$ 3,630.00
 TOTAL REPAIR COST : \$ 14,449.80

Adrian L
 H/s. 20/05/22.
 06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE

Total: 10001.20
 H/s: 8K

8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: