

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/GAI22000779/Vvy3-1	
GREAT AMERICAN INSURANCE COMPANY		Ref:	CS3/GAI22000779/Vvy3
3 TEMASEK AVENUE		Date:	19/05/2022
#16-01 CENTENNIAL TOWER			
SINGAPORE 039190			
		Code:	GAI
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PA 6585U	Veh. Inspected	FBN 7600A
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004108,	Excess (\$)	0.00
Assign From	JANELLE TAN KOH MING SHAO	Assign Date	21/01/2022 19/05/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/01/2022	Inspection Date	21/01/2022
Survey held at	CANDYMOTOR WORKSHOP PTE LTD 25 KAKI BUKIT ROAD 4 #01-83 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			