

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD126E

Not Authored
11 Rmp @ 4900/yr
AAD2205-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

18 MAY 2022**SHD126E**

VF1ABL15AUC283335

200303878K

RENAULT

LATITUDE

15/05/2022

SKT2289K/AIG

31/08/2016

PART	LIST
1 BUMPER COVER REAR	\$ <i>Bu</i> 561.70 ✓
1 BUMPER LOWER REAR	\$ <i>Bu</i> 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 98.10 X
1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sn</i> 82.10 X
1 BUMPER RETAINER RH REAR	\$ <i>Sn</i> 59.80 X
1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sn</i> 80.80 X
1 BUMPER RETAINER LH REAR	\$ <i>Sn</i> 54.20 X
1 BUMPER BEAM REAR	\$ <i>Bu</i> 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 114.50 X
1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 114.50 X
1 OUTER PANEL REAR (End Panel)	\$ <i>Bu</i> 745.80 ✓
1 OUTER PANEL REAR (End Panel)TRIM	\$ <i>cm</i> 404.56 ✓
1 SPARE WHEEL PANEL	\$ <i>R</i> 1,229.40 X
1 BOOT REAR	\$ <i>Bu</i> 1,677.20 ✓
1 BOOT LOCK	\$ <i>R</i> 246.60 X
1 BOOT LOCK CATCH	\$ <i>R</i> 41.70 X
1 BOOT FINISHER	\$ <i>Sn</i> 344.70 X
1 BOOT WEATHERSTRIP	\$ <i>Sn</i> 178.20 X
1 BOOT STRUT LH	\$ <i>Sn</i> 145.10 X
1 BOOT STRUT RH	\$ <i>Sn</i> 145.10 X
1 BOOT HINGE LH	\$ <i>R</i> 254.20 X
1 BOOT HINGE RH	\$ <i>R</i> 254.20 X
1 BOOT BADGE 'RENAULT'	\$ <i>me</i> 82.40 ✓
1 BOOT BADGE	\$ <i>me</i> 95.80 ✓
1 TAILLAMP LH	\$ <i>mgcm</i> 401.40 ✓
1 TAILLAMP RH	\$ <i>Sn</i> 401.40 X
	\$ 8,773.16
10%	\$ 877.32
	\$ 7,895.84

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD126E**Specical Nett**

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	80.00	3050
1 REAR BOOT STICKER '6555-3333'	\$	80.00	3050
1 REAR BUMPER ADVERTISEMENT	\$	100.00	X
1 LICENSE PLATE WITH HOLDER REAR	\$	120.00	X
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
TOTAL	\$	1,752.00	
TOTAL PARTS	\$	9,647.84	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	6600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	6000
To Rust-Proofing Of The Affected Areas.	\$	170.00	600
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	600
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD126E

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ 170.00 *601*

To transfer of rear windscreen fittings and conduct
water seepage test. \$ *na* 170.00 *X*

To check steering geometry and computer wheel
alignment \$ *na* 220.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ 7,880.00

Over All Total \$ 25,423.69

(LUMP SUM)

Repair Days

20 DAYS
5 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: