

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0393/2022/JT
DATE : 17-May-22
WIP : 23850

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR RAJIV VU
ADDRESS : 235 ALEXANDRA ROAD
#04-08
SINGAPORE 289843
TELEPHONE : HP +65 90623735
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100399139-07
VEHICLE NO : **SKL 8061 C**
MODEL CODE : AUDI A6 C7 2.0 TFSI MU
MODEL YEAR : 26/12/2013
ENGINE NO : CDN 378083
CHASSIS NO : WAUZZZ4G9EN057247
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Apr-22
PLACE OF ACCIDENT : GLENEAGLES HOSPITAL CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 8061 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS.	S/N \$	600.00	
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$	400.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	
TOTAL LABOUR CHARGES		:	\$ 3,160.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 8061 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,600.00	
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	
8	TO DISMANTLE AND REINSTALL REAR BUMPER AND LHS SILL PANEL TRIM. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTLL ALL PARTS REMOVED.	\$ 7,200.00	
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$ 7,500.00	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 20,052.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 8061 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR FENDER - LH	1	\$ 4,870.00	
2	REAR WINDSCREEN	1	\$ 1,307.00	
3	PRIMER	2	\$ 44.00	
4	QUARTER WINDOW - LH	1	\$ 348.00	
5	REAR SILL TRIM STRIP - LH	1	\$ 133.00	
6	REAR BUMPER STONE GUARD FILM - LH	1	\$ 133.00	
7	REAR SILL PANEL TRIM CLIP ATTACHMENT PARTS	1	\$ 111.00	
8	REAR SILL PANEL TRIM ADHESIVE TAPES	1	\$ 18.00	
9	REAR DOOR - LH	1	\$ 4,760.00	
10	REAR DOOR ATTACHMENT PARTS	1	\$ 129.00	
11	REAR DOOR OUTER SEAL	1	\$ 256.00	
12	BONDING AGENT	1	\$ 51.00	
13	CLEANING SOLUTION	1	\$ 74.00	
14	APPLICATOR	1	\$ 8.00	
15	REAR DOOR SEAL OUTER	1	\$ 332.00	
16	REAR DOOR CATCH - LH	1	TBC	
17	REAR DOOR HANDLE EXTERIOR TRIM PLATE - LH	1	\$ 548.00	
18	REAR DOOR HANDLE EXTERIOR CAP UPPER PART - LH	1	\$ 97.00	
19	REAR BUMPER GUIDE SECTION - LH LOWER	1	\$ 60.00	
20	REAR WHEEL HOUSING LINER - LH	1	\$ 299.00	
SUB TOTAL SPARE PARTS		:	\$ 13,578.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 8061 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	ARYLIC SEALANT	S/N	\$ 180.00	
22	CAVITY WAX	S/N	\$ 140.00	
23	STONE CHIP	S/N	\$ 180.00	
24	METAL FILLER POWDER	S/N	\$ 280.00	
25	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
26	1/4 GLASS SEALANT	S/N	\$ 100.00	
27	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			: \$ 15,008.00	
TOTAL LABOUR CHARGES			: \$ 20,052.00	
GRAND TOTAL			: \$ 35,060.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT