

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 23 May 2022

Preliminary Advice

Vehicle No	: SKL8061C	Accident Date	: 30/04/2022
Make	: AUDI A6	Policy No.	: 2100399139-07
Assignment Date	: 20/05/2022	Excess	: S\$800.00
Date of Inspection	: 19/05/2022	Est. Duration of Repair	: 13
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 35,060.00
Revised Amount	:S\$ 17,378.00
Check Items (Estimated)	:S\$ 350.00
Total	:S\$ 17,728.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 50,000.00
COE / PARF Rebate	:S\$ 35,759.00

Salvage Value	:S\$
Margin for Repair	:S\$ 14,241.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :
Pending for repair cost from repairer.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.