

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0393/2022/JT
DATE : 17-May-22
WIP : 23850

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Dear Adrian,

13 days - ok

OWNER'S NAME : MR RAJIV VU
ADDRESS : 235 ALEXANDRA ROAD
#04-08
SINGAPORE 289843
TELEPHONE : HP +65 90623735
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100399139-07
VEHICLE NO : **SKL 8061 C**
MODEL CODE : AUDI A6 C7 2.0 TFSI MU
MODEL YEAR : 26/12/2013
ENGINE NO : CDN 378083
CHASSIS NO : WAUZZZ4G9EN057247
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Apr-22
PLACE OF ACCIDENT : GLENEAGLES HOSPITAL CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 8061 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00		
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS.	S/N \$	600.00	\$	600.00
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	\$	150.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$	400.00		
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	\$	1,600.00
TOTAL LABOUR CHARGES		:	\$ 3,160.00	\$	2,350.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 8061 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 2,350.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,600.00	\$ 1,600.00
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	
8	TO DISMANTLE AND REINSTALL REAR BUMPER AND LHS SILL PANEL TRIM. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTLL ALL PARTS REMOVED.	\$ 7,200.00	\$ 3,000.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$ 7,500.00	\$ 1,525.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 20,052.00	\$ 8,667.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 8061 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR FENDER - LH	1	\$ 4,870.00	\$	3,896.00
2	REAR WINDSCREEN	1	\$ 1,307.00	\$	1,045.60
3	PRIMER	2	\$ 44.00	\$	34.72
4	QUARTER WINDOW - LH	1	\$ 348.00	\$	278.00
5	REAR SILL TRIM STRIP - LH	1	\$ 133.00	\$	106.00
6	REAR BUMPER STONE GUARD FILM - LH	1	\$ 133.00		
7	REAR SILL PANEL TRIM CLIP ATTACHMENT PARTS	1	\$ 111.00	\$	88.80
8	REAR SILL PANEL TRIM ADHESIVE TAPES	1	\$ 18.00	\$	14.24
9	REAR DOOR - LH	1	\$ 4,760.00		
10	REAR DOOR ATTACHMENT PARTS	1	\$ 129.00		
11	REAR DOOR OUTER SEAL	1	\$ 256.00		
12	BONDING AGENT	1	\$ 51.00		
13	CLEANING SOLUTION	1	\$ 74.00		
14	APPLICATOR	1	\$ 8.00		
15	REAR DOOR SEAL OUTER	1	\$ 332.00		
16	REAR DOOR CATCH - LH	1	TBC		
17	REAR DOOR HANDLE EXTERIOR TRIM PLATE - LH	1	\$ 548.00		
18	REAR DOOR HANDLE EXTERIOR CAP UPPER PART - LH	1	\$ 97.00		
19	REAR BUMPER GUIDE SECTION - LH LOWER	1	\$ 60.00		
20	REAR WHEEL HOUSING LINER - LH	1	\$ 299.00		
SUB TOTAL SPARE PARTS		:	\$ 13,578.00	\$	5,463.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 8061 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 5,463.36
21	ARYLIC SEALANT	S/N \$	180.00	\$ 180.00
22	CAVITY WAX	S/N \$	140.00	\$ 140.00
23	STONE CHIP	S/N \$	180.00	\$ 180.00
24	METAL FILLER POWDER	S/N \$	280.00	\$ 280.00
25	REAR WINDSCREEN SEALANT	S/N \$	200.00	\$ 200.00
26	1/4 GLASS SEALANT	S/N \$	100.00	\$ 100.00
27	SUNDRIES	\$	350.00	
TOTAL SPARE PARTS			: \$ 15,008.00	\$ 6,543.36
TOTAL LABOUR CHARGES			: \$ 20,052.00	\$ 8,667.00
GRAND TOTAL			: \$ 35,060.00	\$ 15,210.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-27/07/22