

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 751 B

Xiao Chan.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 ✗	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,700.00 ✗ - 480 <i>sls</i>	
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ✗ <i>sls</i> <i>Pricing??</i>	
5	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00 <i>sls</i> <i>1250</i> <i>500 + 1250</i> <i>sls</i>	
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,000.00 <i>sls</i> <i>Buyer 550</i> <i>Spoiler 300</i>	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓ <i>Wheel Arc v2 = 4</i>	
TOTAL LABOUR CHARGES		: \$ 11,372.00	

Add 3 Days for the replacement of condenser which requires the removal of lock carrier. sls.

10/06/22.

(Please inform LKK when the lock carrier is removed)

Car in 8/6/12

WIP=24038

PREMIUM AUTOMOBILES

Bemil



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B

AIG - Adrian
- 3 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>born</i>	1	\$ 3,008.00	✓
2	FRONT BUMPER FIXING PARTS <i>ren</i>	1	\$ 433.00	+
3	FRONT BUMPER CLOSING ELEMENT UPPER - LH / RH ?	2	\$ 132.00	?
4	FRONT BUMPER TRIM - CENTER <i>Delid</i>	1	\$ 396.00	✓
5	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	✓
6	FRONT BUMPER GRILLE ULTRA SENSOR SUPPORT - LH / RH ?	2	\$ 58.00	?
7	FRONT BUMPER COVER LOWER - CENTER <i>ht</i>	1	\$ 58.00	✓
8	FRONT BUMPER CLOSING ELEMENT - LOWER <i>ren?</i>	1	\$ 212.00	+
9	FRONT BUMPER SPOILER <i>delid</i>	1	\$ 850.00	✓
10	FRONT BUMPER BRACKET <i>n</i>	1	\$ 24.00	?
11	FRONT BUMPER AIR GUIDE GRILLE- LH / RH ? <i>ren</i>	2	\$ 342.00	+
12	FRONT BUMPER AIR GUIDE TRIM - LH / RH	2	\$ 364.00	+
13	FRONT AIR GUIDE GRILLE ULTRA SENSOR SUPPORT - LH / RH ?	2	\$ 58.00	?
14	RADIATOR GRILLE <i>cracked</i>	1	\$ 2,135.00	✓
15	RADIATOR GRILLE STRIKER PLATE <i>cracked</i>	1	\$ 271.00	✓ <i>sls</i>
16	RADIATOR GRILLE COVER CAP <i>ren</i>	1	\$ 256.00	+
17	RADIATOR GRILLE BRACKET ?	1	\$ 46.00	?
18	RADIATOR GRILLE COVER CAP <i>cracked</i>	1	\$ 271.00	✓ <i>sls</i>
19	FRONT CAMERA <i>ren?</i>	1	\$ 1,261.00	+
20	FRONT BUMPER REINFORCEMENT BEAM <i>Beit</i>	1	\$ 974.00	✓ <i>sls</i>
SUB TOTAL SPARE PARTS		:	\$ 11,391.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER FOAM FILLER PIECE <i>Truckd</i>	1	\$ 114.00	✓ <i>h.s.</i>	
22	FRONT BUMPER GUIDE SECTION- LH / RH <i>?</i>	2	\$ 86.00	<i>?</i>	
23	FRONT BUMPER TOP COVER <i>and</i>	1	\$ 137.00	✓	
24	CAUTION STICKER <i>3 new</i>	1	\$ 16.00	✓	
25	AIR COND STICKER	1	\$ 9.00	✓	
26	FRONT PARKING AID SENSOR <i>new</i>	4	\$ 1,060.00	+	
27	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 10.00	+	
28	FRONT BUMPER WIRING SET <i>snapped</i>	1	\$ 637.00	✓ <i>h.s.</i>	
29	HORN - LH / RH <i>2 new</i>	2	\$ 298.00	+	
30	HORN SUPPORT - LH / RH	2	\$ 50.00	+	
31	HEADLIGHT MOUNTING (LH / RH) <i>2 new</i>	2	\$ 264.00	+	
32	HEADLIGHT - LH / RH	2	\$ 11,904.00	+	
33	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 462.00	+	
34	LIFT CYLINDER HOSE <i>lit.</i>	1	\$ 92.00	✓ <i>h.s.</i>	
35	LOCK CARRIER <i>new</i>	1	\$ 1,412.00	+	
36	A/C CONDENSER <i>Debit</i>	1	\$ 605.00	✓ <i>h.s.</i>	
37	TEMPERATURE SENSOR HOLDER <i>Dmgd.</i>	1	\$ 9.00	✓ <i>h.s.</i>	
38	ADDITIONAL RADIATOR <i>3 new</i>	1	\$ 982.00	+	
39	RADIATOR	1	\$ 1,090.00	+	
40	RADIATOR AIR GUIDE - UPPER / LOWER <i>Dmgd</i>	2	\$ 96.00	✓ <i>h.s.</i>	
SUB TOTAL SPARE PARTS			\$ 19,333.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	RADIATOR COOLANT	6	\$	282.00	+
42	RADIATOR AIR GUIDE OUTER - LH / RH	2	\$	86.00	+
43	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	520.00	+
44	FRONT WHEEL HOUSING LINER COVER - LH / RH	2	\$	36.00	+
45	FRONT WHEEL ARCH COVER - LH / RH	2	\$	1,132.00	✓
46	FRONT NO PLATE	S/N	\$	120.00	✓
47	SUNDRIES		\$	350.00	✓
TOTAL SPARE PARTS		:	\$	33,250.00	
TOTAL LABOUR CHARGES		:	\$	11,372.00	
GRAND TOTAL		:	\$	44,622.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.