



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0391/2022/JT  
DATE : 17-May-22  
WIP : 24038

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/5/22

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KALUSKAR PRAJAKTA SUBODH  
ADDRESS : 68 FLORA ROAD  
SINGAPORE 506713  
TELEPHONE : HP +65 92728079  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210077579  
VEHICLE NO : **SMU 751 B**  
MODEL CODE : AUDI Q3 SB 1.4 TFSI  
MODEL YEAR : 26/7/2021  
ENGINE NO : CZD C40998  
CHASSIS NO : WAUZZZF33M1124165  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 13-May-22  
PLACE OF ACCIDENT : TAMPINES AVE 7 (OPP ESSO PETROL PUMP)

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 751 B**

| S/N                         | NATURE OF JOBS                                                                                                                                                                   | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                 | S/N \$ 480.00         | ✓                          |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                           | S/N \$ 800.00         | X                          |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.                                                                  | S/N \$ 1,700.00       | X                          |
| 4                           | TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.                                                                                                                             | S/N \$ 1,200.00       | X                          |
| 5                           | TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 4,000.00           | 500                        |
| 6                           | TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.                                                                                             | \$ 3,000.00           | 1250                       |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                   | S/N \$ 192.00         | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                  | <b>: \$ 11,372.00</b> |                            |

Buyer 550  
spoiler 300  
Wheel Arc x 2 = 400

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B**

|                              |                                                         |     | DAMAGED PARTS & PRICES |         |   |
|------------------------------|---------------------------------------------------------|-----|------------------------|---------|---|
| S/N                          | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS |   |
| 1                            | FRONT BUMPER <i>born</i>                                | 1   | \$ 3,008.00            | ✓       |   |
| 2                            | FRONT BUMPER FIXING PARTS <i>new</i>                    | 1   | \$ 433.00              | +       |   |
| 3                            | FRONT BUMPER CLOSING ELEMENT UPPER - LH / RH ?          | 2   | \$ 132.00              | ?       |   |
| 4                            | FRONT BUMPER TRIM - CENTER <i>Del-d</i>                 | 1   | \$ 396.00              | ✓       |   |
| 5                            | FRONT BUMPER GRILLE - CENTER                            | 1   | \$ 242.00              | ✓       |   |
| 6                            | FRONT BUMPER GRILLE ULTRA SENSOR SUPPORT - LH / RH ?    | 2   | \$ 58.00               | ?       |   |
| 7                            | FRONT BUMPER COVER LOWER - CENTER <i>at</i>             | 1   | \$ 58.00               | ✓       |   |
| 8                            | FRONT BUMPER CLOSING ELEMENT - LOWER <i>new?</i>        | 1   | \$ 212.00              | +       | ? |
| 9                            | FRONT BUMPER SPOILER <i>Del-d</i>                       | 1   | \$ 850.00              | ✓       |   |
| 10                           | FRONT BUMPER BRACKET ?                                  | 1   | \$ 24.00               | ?       |   |
| 11                           | FRONT BUMPER AIR GUIDE GRILLE- LH / RH <i>new</i>       | 2   | \$ 342.00              | +       |   |
| 12                           | FRONT BUMPER AIR GUIDE TRIM - LH / RH                   | 2   | \$ 364.00              | +       |   |
| 13                           | FRONT AIR GUIDE GRILLE ULTRA SENSOR SUPPORT - LH / RH ? | 2   | \$ 58.00               | ?       |   |
| 14                           | RADIATOR GRILLE <i>Del-d</i>                            | 1   | \$ 2,135.00            | ✓       |   |
| 15                           | RADIATOR GRILLE STRIKER PLATE ?                         | 1   | \$ 271.00              | ?       |   |
| 16                           | RADIATOR GRILLE COVER CAP <i>new</i>                    | 1   | \$ 256.00              | +       |   |
| 17                           | RADIATOR GRILLE BRACKET ?                               | 1   | \$ 46.00               | ?       |   |
| 18                           | RADIATOR GRILLE COVER CAP <i>new</i>                    | 1   | \$ 271.00              | +       |   |
| 19                           | FRONT CAMERA <i>new?</i>                                | 1   | \$ 1,261.00            | +       | ? |
| 20                           | FRONT BUMPER REINFORCEMENT BEAM ?                       | 1   | \$ 974.00              | ?       |   |
| <b>SUB TOTAL SPARE PARTS</b> |                                                         | :   | <b>\$ 11,391.00</b>    |         |   |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B**

| S/N                          | PARTS DESCRIPTION                             | QTY | DAMAGED PARTS & PRICES |                  | REMARKS |
|------------------------------|-----------------------------------------------|-----|------------------------|------------------|---------|
|                              |                                               |     | S/NETT                 |                  |         |
| 21                           | FRONT BUMPER FOAM FILLER PIECE ?              | 1   | \$                     | 114.00           | ?       |
| 22                           | FRONT BUMPER GUIDE SECTION- LH / RH ?         | 2   | \$                     | 86.00            | ?       |
| 23                           | FRONT BUMPER TOP COVER <i>could</i>           | 1   | \$                     | 137.00           | ✓       |
| 24                           | CAUTION STICKER <i>3 new</i>                  | 1   | \$                     | 16.00            | ✓       |
| 25                           | AIR COND STICKER                              | 1   | \$                     | 9.00             | ✓       |
| 26                           | FRONT PARKING AID SENSOR <i>new</i>           | 4   | \$                     | 1,060.00         | +       |
| 27                           | FRONT PARKING AID SENSOR SEAL RING <i>new</i> | 4   | \$                     | 10.00            | +       |
| 28                           | FRONT BUMPER WIRING SET <i>new</i>            | 1   | \$                     | 637.00           | +       |
| 29                           | HORN - LH / RH <i>3 new</i>                   | 2   | \$                     | 298.00           | +       |
| 30                           | HORN SUPPORT - LH / RH                        | 2   | \$                     | 50.00            | +       |
| 31                           | HEADLIGHT MOUNTING - LH / RH <i>3 new</i>     | 2   | \$                     | 264.00           | +       |
| 32                           | HEADLIGHT - LH / RH                           | 2   | \$                     | 11,904.00        | +       |
| 33                           | LIFT CYLINDER - LH / RH <i>3 new</i>          | 2   | \$                     | 462.00           | +       |
| 34                           | LIFT CYLINDER HOSE                            | 1   | \$                     | 92.00            | +       |
| 35                           | LOCK CARRIER <i>3 new</i>                     | 1   | \$                     | 1,412.00         | +       |
| 36                           | A/C CONDENSER                                 | 1   | \$                     | 605.00           | +       |
| 37                           | TEMPERATURE SENSOR HOLDER <i>2</i>            | 1   | \$                     | 9.00             | +       |
| 38                           | ADDITIONAL RADIATOR <i>1 new</i>              | 1   | \$                     | 982.00           | +       |
| 39                           | RADIATOR                                      | 1   | \$                     | 1,090.00         | +       |
| 40                           | RADIATOR AIR GUIDE - UPPER / LOWER <i>2</i>   | 2   | \$                     | 96.00            | +       |
| <b>SUB TOTAL SPARE PARTS</b> |                                               | :   | \$                     | <b>19,333.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B**

|                             |                                           |     | DAMAGED PARTS & PRICES |                  |
|-----------------------------|-------------------------------------------|-----|------------------------|------------------|
| S/N                         | PARTS DESCRIPTION                         | QTY | S/NETT                 | REMARKS          |
| 41                          | RADIATOR COOLANT                          | 6   | \$ 282.00              | +                |
| 42                          | RADIATOR AIR GUIDE OUTER - LH / RH        | 2   | \$ 86.00               | +                |
| 43                          | FRONT WHEEL HOUSING LINER - LH / RH       | 2   | \$ 520.00              | +                |
| 44                          | FRONT WHEEL HOUSING LINER COVER - LH / RH | 2   | \$ 36.00               | +                |
| 45                          | FRONT WHEEL ARCH COVER - LH / RH          | 2   | \$ 1,132.00            | ✓                |
| 46                          | FRONT NO PLATE                            | S/N | \$ 120.00              | ✗ ? (Pricing ??) |
| 47                          | SUNDRIES                                  |     | \$ 350.00              | ✗ ?              |
| <b>TOTAL SPARE PARTS</b>    |                                           | :   | \$ 33,250.00           |                  |
| <b>TOTAL LABOUR CHARGES</b> |                                           | :   | \$ 11,372.00           |                  |
| <b>GRAND TOTAL</b>          |                                           | :   | \$ 44,622.00           |                  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian L  
19/05/22

are Authorised, 03 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT