

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0391/2022/JT
DATE : 17-May-22
WIP : 24038

Xiao Chen.
06 days H/S.
\$14797.84

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KALUSKAR PRAJAKTA SUBODH
ADDRESS : 68 FLORA ROAD
SINGAPORE 506713
TELEPHONE : HP +65 92728079
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210077579
VEHICLE NO : **SMU 751 B**
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 26/7/2021
ENGINE NO : CZD C40998
CHASSIS NO : WAUZZZF33M1124165
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-May-22
PLACE OF ACCIDENT : TAMPINES AVE 7 (OPP ESSO PETROL PUMP)

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAL@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 751 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 480 1,700.00	X ✓ H.S.
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	X ✓
5	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2000 4,000.00	500
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 1250 3,000.00	Buyer SSO Sporter 300 Wheel Arch x 2 = 400
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,372.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>born</i>	1	\$ 3,008.00	2406.80 2406
2	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 433.00	+
3	FRONT BUMPER CLOSING ELEMENT UPPER - LH / RH <i>Not nec</i>	2	\$ 132.00	? X
4	FRONT BUMPER TRIM - CENTER <i>Del'd</i>	1	\$ 396.00	✓ 316.40
5	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	✓ 193.60
6	FRONT BUMPER GRILLE ULTRA SENSOR SUPPORT - LH / RH <i>Not nec</i>	2	\$ 58.00	? X
7	FRONT BUMPER COVER LOWER - CENTER <i>at</i>	1	\$ 58.00	✓ 45.68 ✓
8	FRONT BUMPER CLOSING ELEMENT - LOWER <i>Not nec</i>	1	\$ 212.00	? X
9	FRONT BUMPER SPOILER <i>Del'd</i>	1	\$ 850.00	✓ 679.60
10	FRONT BUMPER BRACKET <i>Not nec</i>	1	\$ 24.00	? X
11	FRONT BUMPER AIR GUIDE GRILLE- LH / RH <i>neu</i>	2	\$ 342.00	+
12	FRONT BUMPER AIR GUIDE TRIM - LH / RH	2	\$ 364.00	+
13	FRONT AIR GUIDE GRILLE ULTRA SENSOR SUPPORT - LH / RH <i>Not nec</i>	2	\$ 58.00	? X
14	RADIATOR GRILLE <i>Crack'd</i>	1	\$ 2,135.00	✓ 1708
15	RADIATOR GRILLE STRIKER PLATE <i>Crack'd.</i>	1	\$ 271.00	? 216.80 ✓
16	RADIATOR GRILLE COVER CAP <i>neu</i>	1	\$ 256.00	+
17	RADIATOR GRILLE BRACKET <i>Not nec</i>	1	\$ 46.00	? X
18	RADIATOR GRILLE COVER CAP <i>crack'd.</i>	1	\$ 271.00	? 216.80 ✓
19	FRONT CAMERA <i>Not nec</i>	1	\$ 1,261.00	? X
20	FRONT BUMPER REINFORCEMENT BEAM <i>Bent.</i>	1	\$ 974.00	? 778.80 ✓
SUB TOTAL SPARE PARTS			\$ 11,391.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER FOAM FILLER PIECE <i>cracked.</i>	1	\$ 114.00	91.20 ✓
22	FRONT BUMPER GUIDE SECTION- LH / RH <i>Not Rec</i>	2	\$ 86.00	X
23	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 137.00	109.60 ✓
24	CAUTION STICKER <i>3 Rec</i>	1	\$ 16.00	12.40 ✓
25	AIR COND STICKER	1	\$ 9.00	6.64 ✓
26	FRONT PARKING AID SENSOR <i>Not in</i>	4	\$ 1,060.00	+
27	FRONT PARKING AID SENSOR SEAL RING <i>Not Rec</i>	4	\$ 10.00	+
28	FRONT BUMPER WIRING SET <i>Snapped.</i>	1	\$ 637.00	509.60 ✓
29	HORN - LH / RH <i>3 Rec</i>	2	\$ 298.00	+
30	HORN SUPPORT - LH / RH	2	\$ 50.00	+
31	HEADLIGHT MOUNTING - LH / RH <i>CRA</i>	2	\$ 264.00	210.40 ✓
32	HEADLIGHT - LH / RH	2	\$ 11,904.00	+
33	LIFT CYLINDER - LH / RH <i>Not Rec</i>	2	\$ 462.00	+
34	LIFT CYLINDER HOSE <i>lit.</i>	1	\$ 92.00	73.44 ✓
35	LOCK CARRIER <i>Not Rec</i>	1	\$ 1,412.00	+
36	A/C CONDENSER <i>Dented.</i>	1	\$ 605.00	483.60 ✓
37	TEMPERATURE SENSOR HOLDER <i>Damaged.</i>	1	\$ 9.00	6.48 ✓
38	ADDITIONAL RADIATOR <i>Not Rec</i>	1	\$ 982.00	+
39	RADIATOR <i>Not Rec</i>	1	\$ 1,090.00	+
40	RADIATOR AIR GUIDE - UPPER / LOWER <i>Lower Damaged.</i>	2	\$ 96.00	37.84 ✓
SUB TOTAL SPARE PARTS			\$	19,333.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR COOLANT <i>Not Rec</i>	6	\$ 282.00	+
42	RADIATOR AIR GUIDE OUTER - LH / RH <i>Crushed</i>	2	\$ 86.00	+ 68.16 ✓
43	FRONT WHEEL HOUSING LINER - LH / RH <i>Not Rec</i>	2	\$ 520.00	+
44	FRONT WHEEL HOUSING LINER COVER - LH / RH <i>Not Rec</i>	2	\$ 36.00	+
45	FRONT WHEEL ARCH COVER - LH / RH <i>Me</i>	2	\$ 1,132.00	✓ 904.80
46	FRONT NO PLATE <i>Dented</i>	S/N	\$ 120.00	✓ (Pricing??)
47	SUNDRIES <i>Not Rec</i>		\$ 350.00	+
TOTAL SPARE PARTS		:	\$ 33,250.00	
TOTAL LABOUR CHARGES		:	\$ 11,372.00	
GRAND TOTAL		:	\$ 44,622.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Admin Li
14/05/22

are Authorised, 03 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT