

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0391/2022/JT  
**DATE** : 17-May-22  
**WIP** : 24038

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/5/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**8 days exclude 1 Sunday**

**Johnny Boo - 13 Sep 22**

**OWNER'S NAME** : MR KALUSKAR PRAJAKTA SUBODH  
**ADDRESS** : 68 FLORA ROAD  
SINGAPORE 506713  
**TELEPHONE** : HP +65 92728079  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210077579  
**VEHICLE NO** : **SMU 751 B**  
**MODEL CODE** : AUDI Q3 SB 1.4 TFSI  
**MODEL YEAR** : 26/7/2021  
**ENGINE NO** : CZD C40998  
**CHASSIS NO** : WAUZZZF33M1124165  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 13-May-22  
**PLACE OF ACCIDENT** : TAMPINES AVE 7 (OPP ESSO PETROL PUMP)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

### **ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 751 B**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                         |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                                                       | S/N \$ | 480.00               | \$        | <b>480.00</b>                 |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                                 | S/N \$ | 800.00               |           |                               |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.                                                                                                        | S/N \$ | 1,700.00             | \$        | <b>480.00</b>                 |
| 4                           | TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR <b>R1234</b> .                                                                                                                                                           | S/N \$ | 1,200.00             | \$        | <b>1,200.00</b>               |
| 5                           | TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <b>(Q3 - 3 days for Lock carrier)</b> | \$     | 4,000.00             | \$        | <b>2,000.00</b>               |
| 6                           | TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.                                                                                                                                   | \$     | 3,000.00             | \$        | <b>1,250.00</b>               |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                         | S/N \$ | 192.00               | \$        | <b>192.00</b>                 |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                        | :      | <b>\$ 11,372.00</b>  | <b>\$</b> | <b>5,602.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B**

|                              |                                                       |     | DAMAGED PARTS & PRICES |           |                 |
|------------------------------|-------------------------------------------------------|-----|------------------------|-----------|-----------------|
| S/N                          | PARTS DESCRIPTION                                     | QTY | S/NETT                 | REMARKS   |                 |
| 1                            | FRONT BUMPER                                          | 1   | \$ 3,008.00            | \$        | 2,406.00        |
| 2                            | FRONT BUMPER FIXING PARTS                             | 1   | \$ 433.00              |           |                 |
| 3                            | FRONT BUMPER CLOSING ELEMENT UPPER - LH / RH          | 2   | \$ 132.00              |           |                 |
| 4                            | FRONT BUMPER TRIM - CENTER                            | 1   | \$ 396.00              | \$        | 316.40          |
| 5                            | FRONT BUMPER GRILLE - CENTER                          | 1   | \$ 242.00              | \$        | 193.60          |
| 6                            | FRONT BUMPER GRILLE ULTRA SENSOR SUPPORT - LH / RH    | 2   | \$ 58.00               |           |                 |
| 7                            | FRONT BUMPER COVER LOWER - CENTER                     | 1   | \$ 58.00               | \$        | 45.68           |
| 8                            | FRONT BUMPER CLOSING ELEMENT - LOWER                  | 1   | \$ 212.00              |           |                 |
| 9                            | FRONT BUMPER SPOILER                                  | 1   | \$ 850.00              | \$        | 679.60          |
| 10                           | FRONT BUMPER BRACKET                                  | 1   | \$ 24.00               |           |                 |
| 11                           | FRONT BUMPER AIR GUIDE GRILLE- LH / RH                | 2   | \$ 342.00              |           |                 |
| 12                           | FRONT BUMPER AIR GUIDE TRIM - LH / RH                 | 2   | \$ 364.00              |           |                 |
| 13                           | FRONT AIR GUIDE GRILLE ULTRA SENSOR SUPPORT - LH / RH | 2   | \$ 58.00               |           |                 |
| 14                           | RADIATOR GRILLE                                       | 1   | \$ 2,135.00            | \$        | 1,708.00        |
| 15                           | RADIATOR GRILLE STRIKER PLATE                         | 1   | \$ 271.00              | \$        | 216.80          |
| 16                           | RADIATOR GRILLE COVER CAP                             | 1   | \$ 256.00              |           |                 |
| 17                           | RADIATOR GRILLE BRACKET                               | 1   | \$ 46.00               |           |                 |
| 18                           | RADIATOR GRILLE COVER CAP                             | 1   | \$ 271.00              | \$        | 216.80          |
| 19                           | FRONT CAMERA                                          | 1   | \$ 1,261.00            |           |                 |
| 20                           | FRONT BUMPER REINFORCEMENT BEAM                       | 1   | \$ 974.00              | \$        | 778.80          |
| <b>SUB TOTAL SPARE PARTS</b> |                                                       | :   | <b>\$ 11,391.00</b>    | <b>\$</b> | <b>6,561.68</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B**

|                              |                                     |            | DAMAGED PARTS & PRICES |           |                 |
|------------------------------|-------------------------------------|------------|------------------------|-----------|-----------------|
| S/N                          | PARTS DESCRIPTION                   | QTY        | S/NETT                 | REMARKS   |                 |
|                              |                                     | <b>C/F</b> |                        | <b>\$</b> | <b>6,561.68</b> |
| 21                           | FRONT BUMPER FOAM FILLER PIECE      | 1          | \$ 114.00              | \$        | 91.20           |
| 22                           | FRONT BUMPER GUIDE SECTION- LH / RH | 2          | \$ 86.00               |           |                 |
| 23                           | FRONT BUMPER TOP COVER              | 1          | \$ 137.00              | \$        | 109.60          |
| 24                           | CAUTION STICKER                     | 1          | \$ 16.00               | \$        | 12.40           |
| 25                           | AIR COND STICKER                    | 1          | \$ 9.00                | \$        | 6.64            |
| 26                           | FRONT PARKING AID SENSOR            | 4          | \$ 1,060.00            |           |                 |
| 27                           | FRONT PARKING AID SENSOR SEAL RING  | 4          | \$ 10.00               |           |                 |
| 28                           | FRONT BUMPER WIRING SET             | 1          | \$ 637.00              | \$        | 509.60          |
| 29                           | HORN - LH / RH                      | 2          | \$ 298.00              |           |                 |
| 30                           | HORN SUPPORT - LH / RH              | 2          | \$ 50.00               |           |                 |
| 31                           | HEADLIGHT MOUNTING - LH / RH        | 2          | \$ 264.00              | \$        | 210.40          |
| 32                           | HEADLIGHT - LH / RH                 | 2          | \$ 11,904.00           |           |                 |
| 33                           | LIFT CYLINDER - LH / RH             | 2          | \$ 462.00              |           |                 |
| 34                           | LIFT CYLINDER HOSE                  | 1          | \$ 92.00               | \$        | 73.44           |
| 35                           | LOCK CARRIER                        | 1          | \$ 1,412.00            |           |                 |
| 36                           | A/C CONDENSER                       | 1          | \$ 605.00              | \$        | 483.60          |
| 37                           | TEMPERATURE SENSOR HOLDER           | 1          | \$ 9.00                | \$        | 6.48            |
| 38                           | ADDITIONAL RADIATOR                 | 1          | \$ 982.00              |           |                 |
| 39                           | RADIATOR                            | 1          | \$ 1,090.00            |           |                 |
| 40                           | RADIATOR AIR GUIDE - UPPER / LOWER  | 2          | \$ 96.00               | \$        | 37.84           |
| <b>SUB TOTAL SPARE PARTS</b> |                                     | <b>:</b>   | <b>\$ 19,333.00</b>    | <b>\$</b> | <b>8,102.88</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 751 B**

|                             |                                           |            | DAMAGED PARTS & PRICES |           |                  |
|-----------------------------|-------------------------------------------|------------|------------------------|-----------|------------------|
| S/N                         | PARTS DESCRIPTION                         | QTY        | S/NETT                 | REMARKS   |                  |
|                             |                                           | <b>C/F</b> |                        | <b>\$</b> | <b>8,102.88</b>  |
| 41                          | RADIATOR COOLANT                          | 6          | \$ 282.00              |           |                  |
| 42                          | RADIATOR AIR GUIDE OUTER - LH / RH        | 2          | \$ 86.00               | <b>\$</b> | <b>68.16</b>     |
| 43                          | FRONT WHEEL HOUSING LINER - LH / RH       | 2          | \$ 520.00              |           |                  |
| 44                          | FRONT WHEEL HOUSING LINER COVER - LH / RH | 2          | \$ 36.00               |           |                  |
| 45                          | FRONT WHEEL ARCH COVER - LH / RH          | 2          | \$ 1,132.00            | <b>\$</b> | <b>904.80</b>    |
| 46                          | FRONT NO PLATE                            | S/N        | \$ 120.00              | <b>\$</b> | <b>120.00</b>    |
| 47                          | SUNDRIES                                  |            | \$ 350.00              |           |                  |
| <b>TOTAL SPARE PARTS</b>    |                                           | :          | <b>\$ 33,250.00</b>    | <b>\$</b> | <b>9,195.84</b>  |
| <b>TOTAL LABOUR CHARGES</b> |                                           | :          | <b>\$ 11,372.00</b>    | <b>\$</b> | <b>5,602.00</b>  |
| <b>GRAND TOTAL</b>          |                                           | :          | <b>\$ 44,622.00</b>    | <b>\$</b> | <b>14,797.84</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-22/07/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT