

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

\$14669.60.



05 Days. *

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1509 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 350.00	X → \$ 250 ✓ <i>8.8</i>
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 1,400.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		\$ 4,422.00	

+ 1 day.

Car-in

15/6/22 wip: 23978

Bemi

PREMIUM AUTOMOBILES

ATG



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1509 S

4 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1 S	2,377.00 ✓	1901.60
2	FRONT BUMPER FIXING PARTS <i>Rehd</i>	1 S	393.00 +	
3	FRONT BUMPER SECURING STRIP <i>nn</i>	2 S	79.00 7X	
4	FRONT BUMPER GRILLE - CENTER <i>Rehd</i>	1 S	219.00 +	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Rehd</i>	1 S	293.00 +	
6	FRONT BUMPER AIR GUIDE - LH <i>Rehd</i>	1 S	51.00 +	
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>Rehd</i>	1 S	293.00 +	234
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Rehd</i>	1 S	151.00 + 120.40	
9	FRONT BUMPER TRIM - LH <i>Rehd</i>	1 S	54.00 +	
10	RADIATOR GRILLE <i>Rehd</i>	1 S	1,754.00 -	1403.20
11	FRONT BUMPER FOAM FILLER PIECE <i>Rehd</i>	1 S	212.00 -	169.20
12	FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>	1 S	899.00 -	719.20
13	FRONT BUMPER TOP COVER <i>Rehd</i>	1 S	143.00 +	
14	CAUTION STICKER <i>Rehd</i>	1 S	16.00 +	
15	AIR COND STICKER <i>Rehd</i>	1 S	9.00 +	
16	FRONT BUMPER LOCK CARRIER BRACKET <i>Rehd</i>	1 S	154.00 7X	
17	FRONT BUMPER SUPPORT - LH / RH <i>Rehd</i>	2 S	64.00 +	
18	FRONT BUMPER POP RIVET <i>Rehd</i>	4 S	4.00 ✓	2.88
19	FRONT PARKING AID SENSOR - INNER <i>Rehd</i>	1	TBC	
20	FRONT PARKING AID SENSOR SEAL RING <i>Rehd</i>	4 S	10.00 +	

SUB TOTAL SPARE PARTS

: \$ 7,175.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: N'DRA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1509 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN - LH <i>from</i>	1	\$ 134.00	+	
22	HORN SUPPORT - LH	1	\$ 33.00	+	
23	HEADLIGHT - LH <i>at</i>	1	\$ 8,172.00	✓	<i>HS</i> 6537.60
24	LIFT CYLINDER - LH <i>from</i>	1	\$ 231.00	+	
25	LIFT CYLINDER BRACKET	1	\$ 7.00	+	
26	LIFT CYLINDER CORRUGATED PIPE <i>from</i>	1	\$ 107.00	+	
27	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	+	
28	RADIATOR AIR GUIDE OUTER - LH	1	\$ 51.00	+	
29	RADIATOR AIR GUIDE INNER - LH / RH <i>from</i>	2	\$ 38.00	+	
30	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	+	
31	FRONT NO PLATE <i>me</i>	S/N	\$ 60.00	✓	60
32	SUNDRIES <i>me</i>	\$	350.00	7	16.32
TOTAL SPARE PARTS		:	\$ 16,398.00		
TOTAL LABOUR CHARGES		:	\$ 4,422.00		
GRAND TOTAL		:	\$ 20,820.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.