

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/390/2022/JT
DATE : 14-May-22
WIP : 23978

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/5/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : JIMYONG PTE LTD
ADDRESS : 1001 EUNOS AVENUE 8
#01-30
SINGAPORE 409496
TELEPHONE : HP +65 85227991
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210082161
VEHICLE NO : **SNB 1509 S**
MODEL CODE : A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/7/2021
ENGINE NO : DEM 033421
CHASSIS NO : WAUZZZF40MA080425
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-May-22
PLACE OF ACCIDENT : SLIP ROAD AT WOODLANDS AVE 9
TO WOODLANDS AVE 6

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1509 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 1,400.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,422.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1509 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 393.00	+
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 79.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 293.00	+
6	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 51.00	+
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>new</i>	1	\$ 293.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 151.00	+
9	FRONT BUMPER TRIM - LH <i>new</i>	1	\$ 54.00	+
10	RADIATOR GRILLE <i>conhd</i>	1	\$ 1,754.00	✓
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 212.00	?
12	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 899.00	?
13	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00	+
14	CAUTION STICKER <i>new</i>	1	\$ 16.00	+
15	AIR COND STICKER <i>new</i>	1	\$ 9.00	+
16	FRONT BUMPER LOCK CARRIER BRACKET <i>?</i>	1	\$ 154.00	?
17	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$ 64.00	+
18	FRONT BUMPER POP RIVET <i>new</i>	4	\$ 4.00	✓
19	FRONT PARKING AID SENSOR - INNER <i>new</i>	1	TBC	+
20	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 10.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,175.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1509 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN - LH	1	\$ 134.00	+
22	HORN SUPPORT- LH	1	\$ 33.00	+
23	HEADLIGHT - LH	1	\$ 8,172.00	+
24	LIFT CYLINDER - LH	1	\$ 231.00	+
25	LIFT CYLINDER BRACKET	1	\$ 7.00	+
26	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	+
27	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	+
28	RADIATOR AIR GUIDE OUTER - LH	1	\$ 51.00	+
29	RADIATOR AIR GUIDE INNER - LH / RH	2	\$ 38.00	+
30	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	+
31	FRONT NO PLATE	S/N	\$ 60.00	✓
32	SUNDRIES		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 16,398.00	
TOTAL LABOUR CHARGES		:	\$ 4,422.00	
GRAND TOTAL		:	\$ 20,820.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT