

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1509 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 350.00	X 250 250 ✓ <i>8.8</i>
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 1,400.00	500 500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100 1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		\$ 4,422.00	


+ 1 day.

Car-in 15/6/12 wip: 23978

Berni

PREMIUM AUTOMOBILES

AIG



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1509 S

4 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 393.00	+
3	FRONT BUMPER SECURING STRIP ?	2	\$ 79.00	? X
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 293.00	+
6	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 51.00	+
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>cracked</i>	1	\$ 293.00	✓ <i>88.5</i> 234
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 151.00	✓ 120.40
9	FRONT BUMPER TRIM - LH <i>new</i>	1	\$ 54.00	+
10	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,754.00	✓ 1403.20
11	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 212.00	✓ 169.20
12	FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>	1	\$ 899.00	✓ 719.20
13	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00	+
14	CAUTION STICKER <i>new</i>	1	\$ 16.00	+
15	AIR COND STICKER <i>new</i>	1	\$ 9.00	+
16	FRONT BUMPER LOCK CARRIER BRACKET ?	1	\$ 154.00	? X
17	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$ 64.00	+
18	FRONT BUMPER POP RIVET <i>new</i>	4	\$ 4.00	✓ 2.88
19	FRONT PARKING AID SENSOR - INNER <i>new</i>	1	TBC	+
20	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 10.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,175.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1509 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN - LH <i>342 m</i>	1	\$ 134.00	+	
22	HORN SUPPORT - LH	1	\$ 33.00	+	
23	HEADLIGHT - LH <i>cut</i>	1	\$ 8,172.00	✓	<i>h/s</i> 6537.60
24	LIFT CYLINDER - LH <i>342 m</i>	1	\$ 231.00	+	
25	LIFT CYLINDER BRACKET	1	\$ 7.00	+	
26	LIFT CYLINDER CORRUGATED PIPE <i>342 m</i>	1	\$ 107.00	+	
27	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	+	
28	RADIATOR AIR GUIDE OUTER - LH	1	\$ 51.00	+	
29	RADIATOR AIR GUIDE INNER - LH / RH <i>342 m</i>	2	\$ 38.00	+	
30	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	+	
31	FRONT NO PLATE <i>me</i>	S/N	\$ 60.00	✓	60
32	SUNDRIES		\$ 350.00	?	16.32
TOTAL SPARE PARTS		:	\$ 16,398.00		
TOTAL LABOUR CHARGES		:	\$ 4,422.00		
GRAND TOTAL		:	\$ 20,820.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.