

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0410/2022/JT
DATE : 19-May-22
WIP : 24487

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/5/22

HL ASSURANCE Pte Ltd

11 KEPPEL ROAD

#11-01 ABI PLAZA

SINGAPORE 089057

Attn: Motor Claims Dept

Tel: 65 6922 6017 - Fax: 65 6224 1923

Hi Adrian,

3 days - ok - Jy - 4 Jul 22

OWNER'S NAME : MR JOEL GAY
ADDRESS : 87 DAWSON ROAD
#45-17
SINGAPORE 141087
TELEPHONE : HP +65 96374550
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : MP320159
VEHICLE NO : SLJ 2244 E
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 30/11/2016
ENGINE NO : CVN 018177
CHASSIS NO : WAUZZZF44HA031797
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-May-22
PLACE OF ACCIDENT : RAFFLES CITY BASEMENT CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLJ 2244 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENOSR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	350.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$	700.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$	700.00
5	SUPPLEMENTARY	\$	331.70	\$	331.70
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 4,283.70	\$	2,273.70

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 2244 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	\$ 150.50
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
8	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
10	FRONT BUMPER TOP COVER	1	\$ 143.00	
11	CAUTION STICKER	1	\$ 16.00	
12	AIR COND STICKER	1	\$ 9.00	
13	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	
14	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
15	FRONT BUMPER POP RIVET	4	\$ 4.00	
16	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	
17	FRONT WHEEL SPOILER - RH	1	\$ 82.00	
18	HEADLIGHT - RH	1	\$ 8,294.00	\$ 8,294.00
19	LIFT CYLINDER - RH	1	\$ 231.00	
20	LIFT CYLINDER BRACKET	1	\$ 7.00	
SUB TOTAL SPARE PARTS		:	\$ 13,890.00	\$ 8,444.50

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJL 2244 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 8,444.50
21	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
22	RADIATOR AIR GUIDE OUTER - RH	1	\$ 32.00	
23	RADIATOR AIR GUIDE INNER - RH	1	\$ 14.00	
24	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	
25	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 14,412.00	\$ 8,444.50
TOTAL LABOUR CHARGES		:	\$ 4,283.70	\$ 2,273.70
GRAND TOTAL		:	\$ 18,695.70	\$ 10,718.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-28/06/22

**Supplementary Estimate**

GST Reg No. 19-9902271-W

HL ASSURANCE Pte Ltd

11 KEPPEL ROAD

#11-01 ABI PLAZA

Singapore 089057

Attn: Motor Claims Dept

Tel: 65 6922 6017 - Fax: 65 6224 1923

Estimate No.

PA/OD/0410/2022/JT

Date

23-May-22

Service Advisor

TONY

Pages

1 of 1

Regn No

SLJ 2244 E

Model No

AUDI A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labours

1	TOWING FROM ACCIDENT SCENES. BY OWNER	\$ 160.50	\$ 160.50
2	TOWING FROM UBI TO REPORTING CENTRE (2 TRIP) BY OWNER	\$ 171.20	\$ 171.20

GRAND TOTAL		\$ 331.70	\$ 331.70
--------------------	--	------------------	------------------

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT