

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Insurer Reference: OD 0522-8403
Repairer Reference: 047887
Date calculated: 19/05/2022 1:38 PM

Full Report
Registration: YP84C
Printed: 19/05/2022 1:38 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	ERGO Insurance Pte Ltd
Printed by:	Wayne Lim	Currency:	SGD
Claim Reference:	OD 0522-8403	Date of Incident:	13/05/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: ISUZU
 Model: N-SERIES
 Sub Model: NHR
 Model Sheet Number: 37 03 01
 Registration: YP84C
 VIN number: JAANHR85EF7100356
 Odometer:

Model Specs

FROM 11/2002	AIR CONDITIONING	FRONT ELECT WINDOWS	INTERCOOLER
FOG LAMPS	HEADLAMP LEVELLING	TWIN HEADLAMP	ROOF REINFORCEMENT
HYDRO HINGED CAB	DOOR W/OUTS MIRROR	REAR TWIN WHEELS	FLAT BASE BODY
DOUBLE FUEL FILTER	R/DOOR MIRROR	SUSPENSION SETUP	GWR 3.0-3.5T
3.0 LTR 74/85KW	6-SPEED GEARBOX	POWER STEERING	PARAB SPRING 3-LEAF
ANTI LOCK BRAKES	TYRES 165/85 ER 13	WHEELS 4.00 X 13	BRAKE SERVO
VERTICAL EXHAUST SYS	SUSPENSION MED SIZE	SINGLE CAB	TWO COAT METALLIC
PREPARE OFF VEHICLE	BUMPER PAINTED		

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT PANEL (FRONT SCREEN AND INSTRUMENT PANEL REMOVED) INCLUDES: R + R FRONT GRILLE, HEADLAMPS AND CORNER PANEL		62.0	279.00
NO NUMBER	RENEW HEADLAMP PANEL (COMPOSITE WORK)		32.0	144.00
NO NUMBER	RENEW R/A-PILLAR (FRONT SCREEN AND INSTRUMENT PANEL REMOVED) INCLUDES: R + R HEADLAMP, CORNER PANEL, DOOR, FRONT SEAT, ALL ATTACHED PARTS AND TRIMS IN THE REPAIR SECTION		102.0	459.00
NO NUMBER	R + R FRONT PANEL REINFORCEMENT		3.0	13.50
NO NUMBER	R + R FRONT BUMPER		2.0	9.00
NO NUMBER	RENEW FRONT BUMPER (REMOVED)		3.0	13.50

Code	Description	WU	Price SGD
NO NUMBER	R + R WINDSCREEN	15.0	67.50
NO NUMBER	RENEW REAR WIPER MOTOR BRACKET	23.0	103.50
NO NUMBER	RENEW R/DOOR BODY (DOOR REMOVED) INCLUDES: R + R ATTACHED PARTS OF THE DOOR, ALIGN + ADJUST DOOR	15.0	67.50
NO NUMBER	R + R INSTRUMENT PANEL CPL INCLUDES: R + R COMBINATION INSTRUMENT	35.0	157.50
NO NUMBER	DIS + ASS COMPLETE INSTRUMENT PANEL (INSTRUMENT PANEL REMOVED)	7.0	31.50
NO NUMBER	R + R COMPLETE HEATER (INSTRUMENT PANEL AND FRONT GRILLE REMOVED)	13.0	58.50
NO NUMBER	R + R STEERING COLUMN ASSY	12.0	54.00
NO NUMBER	R + R FRONT TORSION BAR	3.0	13.50
NO NUMBER	RENEW L/F CAB BRACKET	3.0	13.50
NO NUMBER	RENEW R/F CAB BRACKET	3.0	13.50
2082	R/SIDE FRAME REPAIR	100.0*	450.00
2280	R/OUTER B-PILLAR REPAIR	100.0*	450.00
2351	ROOF REPAIR	60.0*	270.00
2440	R/ROOF FRAME REPAIR	20.0*	90.00
4236	R/F WHEELARCH PANEL REPAIR	40.0*	180.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		65.30	653.0
Total of Labour			2,938.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINTING	9.0
	L/F CORNER PANEL NEW PART PAINTING	7.0
	R/F CORNER PANEL NEW PART PAINTING	7.0
	FRONT PANEL NEW PART PAINTING	33.0
	LOWER FRONT PANEL SURFACE PAINT	5.0
	RIGHT FRONT DOOR NEW PART PAINTING	17.0
	RIGHT A-PILLAR NEW PART PAINTING	15.0
	RIGHT A-PILLAR REPAIR PAINTING <50%	9.0
	R/OUTER B-PILLAR REPAIR PAINTING <50%	10.0
	R/ROOF FRAME REPAIR PAINTING <50%	7.0
	R/F WHEELARCH PANEL REPAIR PAINTING <50%	8.0
	ROOF REPAIR PAINTING >50%	42.0
	REAR CABIN PANEL REPAIR PAINTING >50%	42.0

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	15.48
0887	L/F CORNER PANEL NEW PART PAINTING	5.16
0888	R/F CORNER PANEL NEW PART PAINTING	5.16
0901	FRONT PANEL NEW PART PAINTING	47.85

Paint Material Per Part

Code	Description	Price SGD
0931	LOWER FRONT PANEL SURFACE PAINT	6.72
1482	RIGHT FRONT DOOR NEW PART PAINTING	49.02
2228	RIGHT A-PILLAR NEW PART PAINTING	13.75
2228	RIGHT A-PILLAR REPAIR PAINTING <50%	8.08
2280	R/OUTER B-PILLAR REPAIR PAINTING <50%	11.31
2440	R/ROOF FRAME REPAIR PAINTING <50%	0.97
4236	R/F WHEELARCH PANEL REPAIR PAINTING <50%	5.81
2351	ROOF REPAIR PAINTING >50%	69.52
3081	REAR CABIN PANEL REPAIR PAINTING >50%	69.52

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			211.0	
Preparation Main Work Metal		2.50	25.0	112.50
Total	10 WU/h	23.60	236.0	1,062.00

Material Cost - Paint

	Price SGD
New Part Painting	136.42
Repair Painting	165.21
Surface-/Blend Paint	6.72
Material-constant Metal Preparation	28.60
Total	336.95

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2001-01-01	Price SGD
4446	BLOWER CPL ✓CRA	8971063153	Original	✓	490.00
1003	BRAKE PIPE 1 ✓		Original	✓	29.00
1004	BRAKE PIPE 2 ✓		Original	✓	29.00
1005	BRAKE PIPE 3 ✓		Original	✓	29.00
0281	FRONT BUMPER ✓BT	8975818710	Original	✓	420.00
0431	FRONT MANUFACT BADGE ✓CRA	8978595561	Original	✓	130.00
0901	FRONT PANEL ✓	8978594233	Original	✓	750.00
6009	FRONT TORSION BAR ✓	8973284880 BT	Original	✓	4,200.00
0906	FRT PANEL REINFORCEMENT ✓	8978513732 BT	Original	✓	600.00
1318	FRT PANEL UPP SEAL ✓	8978530953 NEC	Original	✓	240.00
0410	GRILLE ✓	8978672420	Original	✓	470.00
4445	HEATER BLOWER ✓	8972242862 CRA	Original	✓	1,650.00
4331	INSTRUMENT PANEL ✓	8971959581 CRA	Original	✓	880.00
0317	L/F BUMPER BRACKET ✓	8970936393 BT	Original	✓	100.00
1013	L/F CAB BRACKET ✓	- NEC	Original	✓	80.00
1015	L/F CAB SCREW ✓	NEC	Original	✓	25.00
0887	L/F CORNER PANEL ✓	8978966540	Original	✓	215.00
6011	L/F CTR CAB BRACKET ✓	8970333505	Original	✓	550.00
1453	L/F WIPER ARM ✓	8971845551	Original	x	55.00
1457	L/F WIPER BLADE ✓	8971374682	Original	✓	44.00
0605	L/LOWER H-LAMP MLDG ✓	8978983771	Original	x	155.00
0721	L/REPEATER LAMP LENS ✓	8978551310	Original	✓	325.00

Code	Description	Part Number	Part Source	Price SGD
1000	L/SIGNAL LAMP /CLA	-	Original	✓ 125.00
0931	LOWER FRONT PANEL ✓	8978500498	Original BUC	✓ 600.00
1002	NH STICKER ✓	-	Original NEC	✓ 22.00
1738	R/DOOR MIRROR /D.S	8980516440	Original	✓ 320.00
1011	R/DOOR OPENING TRIM ✓	-	Original DIS	✓ 280.00
1554	R/DOOR SPEAKER X NN	8973170011	Original	X 280.00
1009	R/DOOR STEP GARNISH ✓	-	Original	✓ 140.00
1012	R/DOOR WIRE X NN	-	Original	X 380.00
0318	R/F BUMPER BRACKET X NN	8970936393	Original	X 100.00
1014	R/F CAB BRACKET ✓	-	Original NEC	✓ 80.00
1016	R/F CAB SCREW ✓	-	Original NEC	✓ 25.00
0888	R/F CORNER PANEL /NS	8978966530	Original	✓ 215.00
6012	R/F CTR CAB BRACKET X NN	8970333485	Original	X 550.00
1506	R/F DOOR CHECK /BT	8975816811	Original	✓ 40.00
1510	R/F DOOR FRAME SEAL /NS	8978572055	Original	✓ 160.00
1518	R/F DOOR FRAME SEAL /NS	8978929022	Original	✓ 60.00
1712	R/F DOOR TRIM /NS	8978597216	Original	✓ 245.00
1520	R/F DOOR WINDOW /NS	8978674171	Original	✓ 285.00
0640	R/F FOG LAMP /D.S	8971040600	Original	✓ 285.00
1572	R/F INN DOOR HANDLE	8978666011	Original BT	✓ 19.00
1626	R/F OUT WINDOW MLDG	8978552926	Original	✓ 60.00
1548	R/F WINDOW REGULATOR ✓	8978521157	Original JM	✓ 90.00
1458	R/F WIPER BLADE /Cut	8971374682	Original	✓ 44.00
1578	R/INN DOOR LOCK /BT	8978920982	Original	✓ 142.00
1496	R/LOWER DOOR HINGE	8978520075	Original BT	✓ 95.00
0606	R/LOWER H-LAMP MLDG	8978983561	Original NS	✓ 155.00
1566	R/OUTER DOOR HANDLE	8978677211	Original BT	✓ 45.00
0422	R/RADIATOR SEAL X NN	8970610393	Original	X 16.00
0722	R/REPEATER LAMP LENS	8978551280	Original	✓ 325.00
1006	R/ROUND SIDE MIRROR - /NS	-	Original	✓ 50.00
1001	R/SIGNAL LAMP /D.S	-	Original	✓ 125.00
1488	R/UPPER DOOR HINGE	8978520075	Original BT	✓ 95.00
1008	R/WHEEL ARCH GARNISH /NS	-	Original	✓ 95.00
1552	R/WINDOW MOTOR X NN	8978984770	Original shorted	✓ 195.00
1007	R/WIPER NOZZLE /NS	-	Original	✓ 28.00
0421	RADIATOR GRILLE SEAL	8970610393	Original	X 16.00
2228	RIGHT A-PILLAR /BT	8978590603	Original	✓ 1,290.00
1482	RIGHT FRONT DOOR /NS	8975814301	Original	✓ 880.00
1010	ROOF LINING /NS	-	Original	✓ 400.00
1023	STEERING BRACKET ✓	-	Original BT	✓ 1,180.00
7359	STEERING COLUMN CPL ✓	8974000561	Original BR	✓ 940.00
1423	UPPER MOULDING X NN	8978902143	Original	0.00
1436	WASHER CONTAINER CPL X NN	8978550168	Original cra	✓ 150.00
1401	WINDSCREEN /NS	8978691231	Original	✓ 1,600.00
1410	WINDSCREEN SEAL /NS	8978598567	Original	✓ 175.00
1469	WIPER LINKAGE X NN	8978551530	Original	210.00
1450	WIPER MOTOR X NN	8973613751	Original	390.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Addition(+10.00%)

0.00
24,468.00
2,446.80

Total**26,914.80****Extras**

Code	Description	Price SGD
1017	IU BRACKET -	✓ 25.00*
1018	SEALANT -	✓ 40.00*
1019	SPONGE TAPE -	✓ 20.00*
1020	F/NUMBER PLATE -	✓ 35.00*
1021	RESET - X NN	✓ 200.00*
1022	BRAKE OIL - X NN nec	✓ 50.00*
Total Extras		370.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	24,468.00	
Total Parts	2,446.80	26,914.80
Labour Time Base 10 WU/h		
Total 653.0 WU X 45.00 SGD/h	2,938.50	
Total of Labour		2,938.50
Total Of Extras		370.00
Paint Work Time Base 10 WU/h		
Labour Cost 236.0 WU X 45.00 SGD/h	1,062.00	
Material Cost	336.95	
Total Paint Including Material		1,398.95
Repair Cost Excludes GST		31,622.25
GST (+7.00%)		2,213.56
Repair Cost Included GST	31500.32	33,835.81

-20%: 23550**Comments**

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note**No assessment notes entered.**

Not Authorized.
 Excess \$500
 12 Days.
 L/S After repair parts.
 Gme Q59
 20/5/22

LKK Auto Consultants hence notify
 the Repairer of the following:

- To survey before repair/painting
- To display damaged parts for survey
- Parts price list for repair/painting
- Third party insurance claim basis
- No illegal work
- Supplier's warranty and is subject to the supplier's policy

Acknowledged by Repairer:

Signature:

Date: