(08/13/13) wef	*					
ASS. REC. BY: Marcus REF: CS/CTI	2200475-3/4V43					
<u>A</u>	ASSIGNMENT					
From: Date:	Veh No: SBM 7878X Yr Regn: 11/109/108					
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /					
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or					
To Inspect Vehicle No: 53M 7878× at Workshop m/s	Make: Toyote mark x c.c 2498					
at Workshop m/s 200m	Colour Black A/C: Insured / Std / NI / NA					
of	Sp.Reading /777750 T/Radio: Insured / Std / NI / NA					
Insured: 5NB 4HIE	Eng/No:					
Policy No. DMPCSNW00171492100	C/No: GRX/203058730					
Claims No. SNM22D203390/C02/LEWLC	U/CUZ/LEVVLC Gen. Cong. Good / Fair / Poor / Burnt					
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or					
(Client's Record) Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or					
Make Of Vell.	Modi: Nil / S/Rim / STD A/Rim or					
(Policy Condition)	Tyre Size: F:					
	R: 235/357R/9					
repair at the time of inspection.	TOYO / YOKO or Falken					
Bal. or Market Value:	<u>Front</u> Rear					
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm					
GIA / PR Seen: Consistent?: Yes or No	L/Bal. J mm L/Bal. J mm					
Est. Repairs:	D.O.A. 18/08/22 D.O.I. 20/05/22					
Lum Sum: % 3 Val.: Yes or No	Survey held at					
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or					
Vehicle: IN/OUT OKREER						
Date: Person Contacted: Qer 85000	The U/C / Chassis frame / Body Structure affected due to collision.					
	L7A821977.					
11 alignal. result of	helde-					
0e uneil 31-08-2028 0/5/214/5 \$3400 inhumb St	(red 8357.56, 71%)					
en er i sammer ^e n en						
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4					
1) : Final Report	Resurvey No. of Trip: 2 Survey Fee:					
Date/Time, File Return to? 2) 30/5/22-typist Add F	Transportation:					
2) 30/5/22-typist Add F						
Panart Format : Maximaan	: Interview (\$) Photos					

Report Format: Merimen) Others Lump Sum / I.B.I: (\$ 3400 : Weekend (\$ TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	821C
Vehicle No.:	SBM7878X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	MARK X 2.5 A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	4GR0448841
Chassis No.:	GRX1203058730
Maximum Power Output:	158.0 kW (211 bhp)
Open Market Value:	\$25,958.00
Original Registration Date:	11 Sep 2008
First Registration Date:	11 Sep 2008
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$25,958.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	31 Aug 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$34,991.00
COE Rebate Amount:	\$21,972.00
Total Rebate Amount:	\$21,972.00

The information contained herein is correct as at 20 May 2022

SGCARMART.COM

Sign up

New Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



THE BUSINESS TIMES PropertyBT Podcast

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

03/2010 Toyota Wish \$69800, \$817 Monthly at 2.88%



GV Automobile Centre



3 vehicles

Advertiser Login

tovota mark x 2028

Ways of Selling

Any Category

Advanced Search

Sort by Date Posted

20

C

results/page

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Post an Ad

toyota mark x 2028

> 10 year(s) old

Any

Toyota Mark X 2.5A (COE till

\$55,800

\$9,250 /yr

30-May-2008

2,499 cc

144,000 km

Luxury

Available

Available

High Loan Available, Fast And Easy Loan Approval, Meticulously And Diligently Maintained By Previous Retired Owner With Beautiful Inter...

Posted: 19-May-2022

Toyota Mark X Zio 2.4A (COE till 12/2028)

\$58,800

\$8,890 /yr

30-Dec-2008

2,362 cc

62,000 km

Stationwagon

Available

1 owner! Pristine condition! Rare 7 seater model. Meticulously and diligently maintained by previous retired owner with beautiful interior...

Dew Motoring

Posted: 06-May-2022



Toyota Mark X 2.5A G (COE till 11/2028)

\$60,800

\$9,300 /yr

01-Dec-2008

158,000 km

Luxury

Available

Rare G model! 100% loan available! Monthly around \$1k, superb condition car! Guaranteed no repairs needed, no consignment! View it.

DIRECT OWNER

Posted: 19-Apr-2022

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Reg Date

Eng Cap

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Buy / Rent Cars

Sell Your Car

Aftermarket

Articles

General

New Cars For Sale

Post an Ad

Workshop Directory

Car Reviews

About Us

Used Cars For Sale

Cars For Rent

Sell by Bidding Sell by Consignment Aftermarket Products

Car Advice

Contact Us

Car News

Careers

Car Features

Site Map

Resources

COE Prices

Car Insurance

Used Car Warranty

Carpark Rates

Follow sqCarMart.com











Car Valuation

Bidded Carplates

Car Forum COE Renewal

Car Loan Calculators

SBM 7878 X

REG NO.:

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

the Repairer of the following: To resurvey before/after spray painting

LKK Auto Consultants hence notify

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

24 May 2022 not Arboard

11,757.56

MAKE/MODEL:	TOYOTA MARK X is subject to final approval from Insurance Company			
				20/5/22
ESTIMATED REPAIR	Acknowledged by Repairer R COST FOR THE VEHICLE MENTIONED ABOVE	4 day	, 1	1/543400
	DESCRIPTION Date:		1	AMT(S\$)
	LIST ITEMS			/ (
	Rear windscreen moulding 19	\$		101.65 🗶
	Rear door -RH	\$		1,046.20 🕺
	Rear door lock	\$		428.32 🔨
	Rear door outer handle	\$		60.13 X
	Rear door regulator	\$		185.96
	Rear door regulator motor	\$		646.79 🕺
	Rear door rubber	\$		146.16
	Rocker pand gornish RH CUT Forn	\$ 845	.10	1,280.00
	Rear bumper side retainer 17	\$	1 -	64.70 X
	Rear fender -RH	\$		1,230.50 🔨
	Rear fender air gate	\$		114.40 \(\)
	Rear fender inner shield	\$		82.55 X
	Rear wheel hub with bearing	\$		407.90
	Rear shock absorber	\$		377.50 X
	Rear knuckle arm	\$		849.60
	500	\$		268.70
	Dog Lawar and	\$		374.80X
	0(3)	\$		
	Rear stay arm AA Rear top arm			249.80 X
_	Real top aim	\$		321.08 X
	Less 25%			8,236.74
	Less 25%	\$		2,059.19
		Ф		6,177.56
	SPECIAL NETT ITEMS			
	Rear windscreen sealant	\$		80.00 🗙
	Rear bumper clip (1 set)	\$		60.00 🗡
		\$		400.00 🗡
	300,	\$	2	850.00 800
_	Rear wheel rim -RH Buf / world	\$		1,390.00
	The state of the s	*		2,000.00
S/N	LABOUR CHARGES			
	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00 20
	To remove and refit inner garnishes.	\$		150.00 &
	To remove and refit rear undercarriage.	\$		350.00 120
	To conduct wheel alignment.	\$		180.00 80
	To remove and refit rear windscreen glass.		4 ^	180.00 X
	To remove, refit door fittings and replace damaged parts, transfer all		11	150.00 🗶
	fittings to new door.	Ψ ,	11	100.00 /
	To apply undercoating.	\$	12	200.00 🗶
	Panel beating.	\$		1,500.00
	To re-spray painting on the affected areas.	\$		1,400.00
	to re-spray painting on the anected areas.			
9		\$		4,190.00

GRAND TOTAL:

Page 1 of 1